

# Renault VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Renault/TRIBER/KIGER/--  
VIN: MEEHBC00600042557

Odometer Reading: 151318km  
License Plate: KM34JZGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V17.50

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 9 )

| System                              | Status/DTC                                                                                                                                                                  |
|-------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| INJ(Injection)                      |  1                                                                                       |
| ABS(Anti-lock braking system)       |  0                                                                                       |
| ABG(Airbag / pretensioners)         |  0                                                                                       |
| TDB(Instrument panel)               |  0                                                                                       |
| UCH(Central control unit)           |  0                                                                                     |
| UCC(Communications unit)            |   2 |
| DAV(Variable power assist steering) |  3                                                                                     |
| GW2(Central gateway)                |  0                                                                                     |
| HFM(Hands-free module)              |  2                                                                                     |

## DTC ( 8 )

### INJ(Injection) ( 1 DTC )

| DTC       | Description                                          | Status |
|-----------|------------------------------------------------------|--------|
| DTC090174 | Clutch motor<br>Performance: loss of power or torque | Memory |

### UCC(Communications unit) ( 2 DTCs )

| DTC       | Description                          | Status |
|-----------|--------------------------------------|--------|
| DTC934149 | Computer<br>System internal failures | Memory |
| DTC93514B | Computer<br>Overheating              | Memory |

### DAV(Variable power assist steering) ( 3 DTCs )

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|

|           |                                                            |        |
|-----------|------------------------------------------------------------|--------|
| DTC560116 | Battery voltage 12 V<br>Battery voltage too low            | Memory |
| DTC561B86 | Info. multiplex vehicle speed invalid<br>Invalid signal    | Memory |
| DTCE14F87 | 645 BCM not detected by 1232 EPS CAN-V1<br>Missing message | Memory |

HFM(Hands-free module) ( 2 DTCs )

| DTC       | Description                                                       | Status |
|-----------|-------------------------------------------------------------------|--------|
| DTCA05111 | VER(Steering lock)<br>Short circuit to earth.                     | Memory |
| DTCA0571C | Steering column lock protection<br>Circuit voltage outside limits | Memory |

Technician Notes  
2017304888

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.