

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00000165145

Odometer Reading: 109784km
License Plate: LH22CFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	 2
ABS(Anti-lock braking system)	 3
ABG(Airbag / pretensioners)	 0
TDB(Instrument panel)	 0
UCH(Central control unit)	 1
DAV(Variable power assist steering)	 4
RDO(Radio)	 1

A@AS

DTC (11)

INJ(Injection) (2 DTCs)

DTC	Description	Status
DTC056016	Computer supply voltage Permanent low level	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory

ABS(Anti-lock braking system) (3 DTCs)

DTC	Description	Status
DTC403097	Front left wheel target Component or system operation blocked or jammed	Memory
DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC10000	Injection multiplexed emission missing No communication	Memory

UCH(Central control unit) (1 DTC)

DTC	Description	Status
-----	-------------	--------

DTC952014	Starter relay Open circuit or short circuit to earth	Memory
-----------	---	--------

DAV(Variable power assist steering) (4 DTCs)

DTC	Description	Status
DTC560849	Computer Internal electronic failure	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

RDO(Radio) (1 DTC)

DTC	Description	Status
DTC934262	Unit locked Computer locked	Memory

Technician Notes
2017305805

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.