



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250726110115
Test Time: 2025-07-26 11:01:15
Technician: Sbu

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/320i/--
VIN: WBA3B16060NS53148

Odometer Reading: 195272km
License Plate: CZ21WYGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V23.01

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(16)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	 4
EGS (Electronic Transmission Management)	 0
DSC (Dynamic Stability Control)	 1
ACSM (Airbag-Advanced Crash Safety Module)	 0
KOMBI (Instrument Cluster)	 0
FEM (Front Electronic Module)	 4
ZGM (Central Gateway Module)	 2
EKPS (Electric Fuel Pump Control)	 1
ICM (Integrated Chassis Management)	 0
EPS (Electric Power Steering)	 0
FZD (Roof Function Center)	 0
GWS (Gear Selector Switch)	 0
HUB (Headunit Basis)	 0
CON (Controller)	 0
REM (Rear Electronic Module)	 4
IHKA (Integrated Automatic Heating And A/C System)	 0

DTC (16)

DME (Engine-Digital Motor Electronics) (4 DTCs)

DTC	Description	Status
CD9437	DME, FlexRay: Communication fault	Intermittent



213A21	Vehicle voltage, working area: Voltage too low	Intermittent
213901	Power management: Reduction or shutdown of individual electrical consumer	Intermittent
213501	Power management: Total discharge	Intermittent

DSC (Dynamic Stability Control) (1 DTC)

DTC	Description	Status
480A11	Brake pad wear sensor: Front axle, replace brake pads	Permanent

FEM (Front Electronic Module) (4 DTCs)

DTC	Description	Status
8040B7	De-activation of terminal 15: Top startability limit reached	Intermittent
8040B9	De-activation of terminal 30B: Top startability limit reached	Intermittent
8040BD	Reset or deactivation of terminal 30F	Intermittent
80444D	Inside mirror: Undervoltage detected	Permanent

ZGM (Central Gateway Module) (2 DTCs)

DTC	Description	Status
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent
801C20	ZGM: central fault memory full - no control-unit fault	Permanent

EKPS (Electric Fuel Pump Control) (1 DTC)

DTC	Description	Status
481B13	EKPS: Vehicle driven until tank completely drained of fuel	Intermittent

REM (Rear Electronic Module) (4 DTCs)

DTC	Description	Status
030181	Window regulator, passenger-side door, back: Window regulator on driver's door: relay closing, no output voltage	Permanent
804872	Brake light, left, faulty	Permanent
804874	Brake light, right, faulty	Permanent
804877	Turn indicator, rear right, faulty	Permanent

Technician Notes

2016959304

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.