



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240719103537
Test Time: 2024-07-19 10:35:37
Technician: Travino

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/3'/320d_B47/--
VIN: WBA5V52050AJ68774

Odometer Reading: 121600km
License Plate: LG61DHGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V21.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(22)

System		Status/DTC
DDE (Engine-Diesel Electronics)		10
EGS (Electronic Transmission Management)		1
DSC (Dynamic Stability Control)		1
ACSM (Airbag-Advanced Crash Safety Module)		1
KOMBI (Instrument Cluster)		2
BDC (Body Domain Controller)		3
TRSVc (All Round View Camera)		0
HKFM (Rear Tailgate Function Module)		2
ZGM (Central Gateway Module)		0
PMA (Parking Manoeuvring Assistant)		3
EPS (Electric Power Steering)		0
RAM (Receiver audio module)		4
VIP (Virtual integration system)		0
FLEL (Frontal Light Electronics Left)		2
FLER (Frontal Light Electronics Right)		2
FZD (Roof Function Center)		0
GWS (Gear Selector Switch)		0



FLA (High Beam Assist)		 0
TCB (Combox Emergency Call)		 1
HUH (Headunit High)		 13
CON (Controller)		 0
IHKA (Integrated Automatic Heating And A/C System)		 0

 DTC (45)**DDE (Engine-Diesel Electronics) (10 DTCs)**

DTC	Description	Status
030E0F	Power management: Remote software upgrade deactivated due to ageing battery	Permanent
030E06	Power management: Reduction or shutdown of individual electrical consumer	Intermittent
337F00	Bottom radiator blind, position control: Control deviation	Intermittent
32C300	Bottom radiator blind, plausibility: Control deviation	Intermittent
2E0600	Engine start, plausibility: Fuel pre-supply pressure too low at engine start	Intermittent
321700	Engine start, plausibility: Fuel pre-supply pressure too low upon engine start after vehicle driven until tank completely drained of fuel	Intermittent
249300	Rail pressure monitoring on engine start: Rail pressure too low during engine starting	Intermittent
33AA00	Attempt to start the engine with fault in the fuel system detected	Intermittent
30C400	Bottom radiator blind, plausibility: Blocking	Intermittent
338100	Bottom radiator blind, plausibility: Failure to detect closed limit position	Intermittent

EGS (Electronic Transmission Management) (1 DTC)

DTC	Description	Status
CF2DE1	Signal (engine warm-up switch status) invalid, transmitter DME / DDE	Intermittent

DSC (Dynamic Stability Control) (1 DTC)

DTC	Description	Status
480A11	Brake pad wear sensor: Front axle, replace brake pads	Permanent

ACSM (Airbag-Advanced Crash Safety Module) (1 DTC)

DTC	Description	Status
803185	PDC: Activation not possible	Intermittent

KOMBI (Instrument Cluster) (2 DTCs)

DTC	Description	Status
026004	Instrument panel: Coding: Internal SWT check failed	Permanent
026003	Instrument panel: Coding: External SWT test condition not met	Permanent

BDC (Body Domain Controller) (3 DTCs)

DTC	Description	Status
80402F	Power management, battery condition: Total discharge	Permanent
804415	Radio remote control: Battery undervoltage	Permanent
804A7E	Wireless charging oddments tray: Line fault between aerial amplifier and roof-mounted aerial	Permanent

HKFM (Rear Tailgate Function Module) (2 DTCs)

DTC	Description	Status
801724	HKFM, automatic operation of tailgate: Driving speed exceeds 0 km/h for operating requirement	Permanent
801703	HKFM: Undervoltage detected	Intermittent

PMA (Parking Manoeuvring Assistant) (3 DTCs)

DTC	Description	Status
803206	Ultrasonic sensors: Blindness identified	Intermittent
803207	Ultrasonic sensors: Extraneous noise detected	Intermittent
803265	Ultrasonic sensor, PMA, rear side right: Blindness identified	Intermittent

RAM (Receiver audio module) (4 DTCs)

DTC	Description	Status
023703	External SWT test condition not met	Permanent
023704	Internal SWT check failed	Permanent
B7F480	Audio amplifier (booster): no connection	Intermittent
B7F4B3	Audio amplifier (booster): Reset	Intermittent

FLEL (Frontal Light Electronics Left) (2 DTCs)

DTC	Description	Status
8059EA	Elektronics module laser light: Undervoltage/Overvoltage identified	Intermittent
805A05	Undervoltage detected	Intermittent

FLER (Frontal Light Electronics Right) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

805B85	Undervoltage detected	Intermittent
805B6A	Elektronics module laser light: Undervoltage/Overvoltage identified	Intermittent

TCB (Combox Emergency Call) (1 DTC)

DTC	Description	Status
031786	TCB: Functional limitation of Last State Call	Intermittent

HUH (Headunit High) (13 DTCs)

DTC	Description	Status
031798	HU-H: Functional limitation for Bluetooth audio browsing	Intermittent
E1C600	HU-H: Ethernet: Unexpected communication termination	Intermittent
031794	HU-H: Function restriction telephone calls	Intermittent
B7F867	HU-H: Internal temperature fault	Intermittent
031795	HU-H: Function restriction telephone book	Intermittent
031796	HU-H: Function restriction telephone list	Intermittent
031799	HU-H: Function restriction connection app	Intermittent
03179D	HU-H: Function restriction SMS	Intermittent
031790	HU-H: Function restriction connection establishment / coupling Bluetooth	Intermittent
031797	HU-H: Functional limitation for Bluetooth audio	Intermittent
031791	HU-H: Function resrtriction Bluetooth connection	Intermittent
03179A	HU-H: Function restriction connection Apple CarPlay	Intermittent
031793	HU-H: Function restriction connection WLAN	Intermittent

Technician Notes

2016460350

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.