

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--  
VIN: WDD2220772A114123

Odometer Reading: 3890km  
License Plate: HM02CVGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V25.00

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 8 )

| System                        | Status/DTC                                                                              |
|-------------------------------|-----------------------------------------------------------------------------------------|
| 01 - Engine Control Module 1  |  3   |
| 02 - Transmission electronics |  2   |
| 03 - Brakes 1                 |  0   |
| 10 - Parallel parking 2       |  1   |
| 15 - Airbag                   |  1 |
| 17 - Instrument cluster       |  1 |
| 44 - Power steering           |  1 |
| 55 - Headlamp range control   |  0 |

## DTC ( 9 )

### 01 - Engine Control Module 1 ( 3 DTCs )

| DTC     | Description                             | Status           |
|---------|-----------------------------------------|------------------|
| P006800 | MAP/MAF - Throttle Position Correlation | Passive/Sporadic |
| P227900 | Intake air system leakage               | Passive/Sporadic |
| U112300 | Databus error value received            | Passive/Sporadic |

### 02 - Transmission electronics ( 2 DTCs )

| DTC     | Description                             | Status           |
|---------|-----------------------------------------|------------------|
| U140000 | Function restriction due to low voltage | Passive/Sporadic |
| P060700 | Control Module Performance              | Passive/Sporadic |

### 10 - Parallel parking 2 ( 1 DTC )

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|

|         |                                            |                  |
|---------|--------------------------------------------|------------------|
| U140000 | Function restriction<br>due to low voltage | Passive/Sporadic |
|---------|--------------------------------------------|------------------|

15 - Airbag ( 1 DTC )

| DTC     | Description                                         | Status           |
|---------|-----------------------------------------------------|------------------|
| B100B1B | Driver thorax airbag igniter<br>Resistance too high | Passive/Sporadic |

17 - Instrument cluster ( 1 DTC )

| DTC     | Description                                                | Status           |
|---------|------------------------------------------------------------|------------------|
| U105400 | Information electronics 1 control unit<br>No communication | Passive/Sporadic |

44 - Power steering ( 1 DTC )

| DTC     | Description                       | Status           |
|---------|-----------------------------------|------------------|
| U101100 | Supply voltage<br>Voltage too low | Passive/Sporadic |

Technician Notes  
2017286821

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.