

# MINI VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/MINI/MINI/Cooper S\_B48/--  
 VIN: WMWXM720703C11123

Odometer Reading: 99202km  
 License Plate: HB67DGGP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V19.10

Serial Number: VB8GJCC01482  
 Repair Order Number: --

## System Scanned ( 15 )

System		Status/DTC
DME (Engine-Digital Motor Electronics)		0
EGS (Electronic Transmission Management)		0
DSC (Dynamic Stability Control)		2
ACSM (Airbag-Advanced Crash Safety Module)		2
BDC (Body Domain Controller)		7
ZGM (Central Gateway Module)		1
EPS (Electric Power Steering)		0
CHRONO (Chronometer)		1
ASD (Active Sound Design)		1
FLEL (Frontal Light Electronics Left)		1
FLER (Frontal Light Electronics Right)		1
FZD (Roof Function Center)		1
HUB (Headunit Basis)		6
CON (Controller)		0
IHKA (Integrated Automatic Heating And A/C System)		3

## DTC ( 26 )

### DSC (Dynamic Stability Control) ( 2 DTCs )

DTC	Description	Status
-----	-------------	--------

480A12	Brake pad wear sensor: Rear axle, replace brake pads	Permanent
--------	--	-----------

480A11	Brake pad wear sensor: Front axle, replace brake pads	Permanent
--------	---	-----------

### ACSM (Airbag-Advanced Crash Safety Module) ( 2 DTCs )

DTC	Description	Status
9309C4	Driver's seat belt buckle contact: Open circuit	Intermittent
C94487	ACSM, FlexRay: Communications fault	Intermittent

### BDC (Body Domain Controller) ( 7 DTCs )

DTC	Description	Status
030095	Front passenger door power window regulator: no initialisation present	Permanent
030751	Continuous operation of driving experience switch, right	Intermittent
8040B7	De-activation of terminal 15: Top startability limit reached	Intermittent
8040B9	De-activation of terminal 30B: Top startability limit reached	Intermittent
8040BD	Terminal 30F reset or deactivated	Intermittent
804880	Output, right rear fog light faulty	Permanent
D90D29	Rain-light-solar-condensation sensor: Missing LIN slave	Intermittent

### ZGM (Central Gateway Module) ( 1 DTC )

DTC	Description	Status
801C12	Send Power-Down command due to prevented sleeping	Intermittent

### CHRONO (Chronometer) ( 1 DTC )

DTC	Description	Status
D62C02	Signal (time / date) invalid, transmitter KOMBI	Intermittent

### ASD (Active Sound Design) ( 1 DTC )

DTC	Description	Status
805382	ASD: Undervoltage	Intermittent

### FLEL (Frontal Light Electronics Left) ( 1 DTC )

DTC	Description	Status
8059BD	FLE_L: Undervoltage detected	Intermittent

### FLER (Frontal Light Electronics Right) ( 1 DTC )

DTC	Description	Status
805B37	FLE_R: Undervoltage detected	Intermittent

### FZD (Roof Function Center) ( 1 DTC )

DTC	Description	Status
-----	-------------	--------

801A55 Anti-theft alarm system: The alarm has been activated Permanent

### HUB (Headunit Basis) ( 6 DTCs )

DTC	Description	Status
B7F84F	Microphone 1. Short circuit to ground	Intermittent
B7F85A	Headunit connection to aerial amplifier: Line disconnection, FM1 aerial	Intermittent
B7F86B	HU-B: Undertension	Permanent
B7F8C3	Connection, headunit to CID: No communication	Intermittent
B7F8C6	CID: Reduction in brightness due to excess temperature	Intermittent
B7F8CD	HU connection to aerial amplifier: Line disconnection, FM2 aerial	Intermittent

### IHKA (Integrated Automatic Heating And A/C System) ( 3 DTCs )

DTC	Description	Status
801189	Mixing flap drive, right Specification of desired position failed	Permanent
80118A	Mixing flap drive, right Internal stepper motor fault	Intermittent
E70C21	Mixing flap drive, right does not respond	Intermittent

### Technician Notes

2016200869

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.