



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 02/10/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 02/10/2026        |                     | Kempton Park -           |

## Vehicle Data

|                 |                            |                         |              |
|-----------------|----------------------------|-------------------------|--------------|
| Vehicle Type    | PASSENGER VEHICLE          | Registered Owner        | MFC          |
| Manufacturer    | MITSUBISHI MOTORS          | Registration Number     | BC40JYGP     |
| Model           | LANCER 2.0 GLS [2007-2012] | Register Number         |              |
| VIN             | JMYSNCY4AAU100685          | Date Of First Licensing |              |
| Engine Number   |                            | Last COR                |              |
| Doors           | 4                          | License Expiry Date     |              |
| Color           | SILVER                     | Power / Displacement    |              |
| Year Model      | 2010                       | Paint Finish            | M - METALLIC |
| Km Reading      | 261,751 KM                 | Fuel                    | PETROL       |
| Cab / Body Type | SEDAN                      | Transmission            | MANUAL       |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:

2017306440

DATE

02/10/2026

## Damage

## Repair Way

|                                                       |                                              |
|-------------------------------------------------------|----------------------------------------------|
| Seat Front Right Damaged                              | Repair                                       |
| Seat Rear Torn / Cut                                  | Repair                                       |
| Side Mirror Left Paintwork • Scratched                | Repair                                       |
| Front Bumper Paintwork • Discoloured                  | Repair                                       |
| Bonnet Dented                                         | Repair                                       |
| Bonnet slam plate (Shock tower/ Inner tray) Corrosion | Repair                                       |
| A • Pillar Left Dented                                | Repair                                       |
| A • Pillar Right Dented                               | Repair                                       |
| Front Fender Left Dented                              | Repair                                       |
| Front Fender Right Paintwork • Discoloured            | Repair                                       |
| Rear Fender Left Paintwork • Flaking                  | Repair                                       |
| Rear Fender Right Paintwork • Discoloured             | Repair                                       |
| Door Front Left Dented                                | Repair                                       |
| Door Front Right Paintwork • Discoloured              | Repair                                       |
| Door Rear Left Paintwork • Scratched                  | Repair                                       |
| Door Rear Right Paintwork • Discoloured               | Repair                                       |
| Boot Lid / Hatch door Paintwork • Flaking             | Repair                                       |
| Rear bumper Paintwork • Discoloured                   | Repair                                       |
| Roof Paintwork • Flaking                              | Repair                                       |
| Shock Absorber Front Left Leak                        | Replace                                      |
| Shock Absorber Front Right Leak                       | Replace                                      |
| No license disc                                       | Replace                                      |
| L/F fender liner damage                               | Replace                                      |
| Body exterior                                         | Signs of spray work done on some body panels |
| Body exterior                                         | Discoloring on some body panels              |

## Brakes

## Brake Test Results

|                     | Left               | Right              | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] |                  |                                  |
| Front               | 2.5                | 3.3                | -                |                                  |
| Rear                | 2.0                | 2.1                | -                |                                  |
| Emergency / Parking | 1.9                | 2.3                | -                |                                  |

## Tyres and Rims

## Tyre Specification &amp; Measurement

|             | Size       | Load/Speed Index | Manufacture | Model       | Type* | Production Date | Tread Depth (mm) |
|-------------|------------|------------------|-------------|-------------|-------|-----------------|------------------|
| Front Left  | 205/60R16  | 92H              | Goodride    | Radial rp28 | V     | 3216            | 1 mm             |
| Front Right | 205/60R16  | 92H              | Goodride    | Radial rp28 | V     | 3216            | 1 mm             |
| Rear Left   | 205/60R16  | 107/105T         | Nexen       | Roadian     | V     | 0721            | 3 mm             |
| Rear Right  | 205/65R16  | 107/105T         | Goodyear    | Vector      | V     | 4010            | 3 mm             |
| Spare       | T125/70D16 | 96M              | Dunlop      | Temporary   | V     | 3609            | 4 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System     | Code  | Description   | Status |
|----|------------|-------|---------------|--------|
| 1  | STORED DTC | U0164 | A/CAN TIMEOUT |        |

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

#### General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:

2017306440

DATE

02/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685




## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026



RF TYRE TREAD



RR TYRE TREAD



Spare wheel



Coolant bottle



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:

2017306440

DATE \_\_\_\_\_

02/10/2026



ENGINE 2



## CHASSIS



VIN PLATE OR STICKER



LICENSE DISC MISSING

[illegible]

SHOCK AND BRAKE REPORT

[illegible]

DIAGNOSTIC REPORT PAGE 1

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)


VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026



DIAGNOSTIC REPORT PAGE 2



Bonnet slam plate (Shock tower/ Inner tray)



Water level



Bonnet



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:

2017306440

DATE

02/10/2026



Front Fender Left



A • Pillar Left



Door Front Left



Side Mirror Left



Roof



Door Rear Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026



Door Front Right



Front Fender Right



A • Pillar Right



Seat Front Right



Seat Rear



Shock Absorber Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685



## CONDITION REPORT



Report No:  
2017306440  
DATE  
02/10/2026



Shock Absorber Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JMYSNCY4AAU100685