



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 25/09/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 25/09/2026        |                     | Kempton Park -           |

## Vehicle Data

|                 |                    |                         |              |
|-----------------|--------------------|-------------------------|--------------|
| Vehicle Type    | PASSENGER VEHICLE  | Registered Owner        | MFC          |
| Manufacturer    | TOYOTA             | Registration Number     | KT48KMGP     |
| Model           | URBAN CRUISER      | Register Number         |              |
| VIN             | JTDPYGGJ1S00976829 | Date Of First Licensing |              |
| Engine Number   |                    | Last COR                |              |
| Doors           | 5                  | License Expiry Date     | 31/08/2026   |
| Color           | GREY               | Power / Displacement    |              |
| Year Model      |                    | Paint Finish            | TWO COAT UNI |
| Km Reading      | 78,532 KM          | Fuel                    | PETROL       |
| Cab / Body Type | HATCHBACK          | Transmission            | MANUAL       |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JTDPYGGJ1S00976829



## CONDITION REPORT



Report No:

2017303166

DATE

25/09/2026

## Damage

## Repair Way

|                                                  |         |
|--------------------------------------------------|---------|
| Hood Lining Dirty                                | Repair  |
| Bonnet Dented                                    | Repair  |
| C • Pillar Right Dented                          | Repair  |
| Rear Fender Left Dented                          | Repair  |
| Rear Fender Right Dented                         | Repair  |
| Boot Lid / Hatch door Dented                     | Repair  |
| Roof Dented                                      | Repair  |
| Windscreen Chipped                               | Repair  |
| Service Brake Performance Rear Axle Left / Right | Repair  |
| Difference out of legal range                    |         |
| Tyre Front Left Worn                             | Replace |
| Tyre Front Right Worn                            | Replace |
| Tyre Rear Right Damaged                          | Replace |
| Deceleration service brake defective             | Repair  |



## Brakes

## Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 2.83               | 2.99               | -                |                                  |
| Rear                | 1.46               | 0.74               | -                |                                  |
| Emergency / Parking | 1.95               | 2.18               | -                |                                  |

## Tyres and Rims

## Tyre Specification &amp; Measurement

|             | Size        | Load/Speed Index | Manufacture | Model    | Type* | Production Date | Tread Depth (mm) |
|-------------|-------------|------------------|-------------|----------|-------|-----------------|------------------|
| Front Left  | 215/60 R16  | 95V              | Bridgestone | Turanza  | V     | 3120            | 0 mm             |
| Front Right | 215/60 R16  | 95V              | Bridgestone | Turanza  | V     | 3120            | 0 mm             |
| Rear Left   | 205/65 R16C | 103H             | Hankook     | Vantra   | V     | 3018            | 2 mm             |
| Rear Right  | 205/65 R16  | 95V              | Michelin    | GreenX   | V     | 1822            | 0 mm             |
| Spare       | 215/60 R16  | 95H              | MRF         | Wanderer | V     | 2022            | 4 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JTDPGJ1S00976829



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System      | Code     | Description                  | Status |
|----|-------------|----------|------------------------------|--------|
| 1  | SRS(AIRBAG) | B1004-18 | POWER SUPPLY VOLTAGE TOO LOW |        |

### Inspection Conditions

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches on body panels

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JTDPYGJ1S00976829



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026

[illegible]

Brake and shock absorber report

| AUTOL                           |  | AUTOL              |  |
|---------------------------------|--|--------------------|--|
| AUTOL                           |  | AUTOL              |  |
| Toyota VEHICL DIAGNOSTIC DEFECT |  |                    |  |
| 1. ENGINE                       |  | 2. TRANSMISSION    |  |
| 3. DRIVE SHAFTS                 |  | 4. SUSPENSION      |  |
| 5. STEERING                     |  | 6. BRAKES          |  |
| 7. ELECTRICAL                   |  | 8. BODY            |  |
| 9. SAFETY                       |  | 10. OTHER          |  |
| 11. TIRE                        |  | 12. WASH/WAX       |  |
| 13. AIR CONDITION               |  | 14. AUDIO/VIDEO    |  |
| 15. LIGHTS                      |  | 16. MISCELLANEOUS  |  |
| 17. MAINTENANCE                 |  | 18. INSPECTION     |  |
| 19. TIRE                        |  | 20. WASH/WAX       |  |
| 21. AIR CONDITION               |  | 22. AUDIO/VIDEO    |  |
| 23. LIGHTS                      |  | 24. MISCELLANEOUS  |  |
| 25. MAINTENANCE                 |  | 26. INSPECTION     |  |
| 27. TIRE                        |  | 28. WASH/WAX       |  |
| 29. AIR CONDITION               |  | 30. AUDIO/VIDEO    |  |
| 31. LIGHTS                      |  | 32. MISCELLANEOUS  |  |
| 33. MAINTENANCE                 |  | 34. INSPECTION     |  |
| 35. TIRE                        |  | 36. WASH/WAX       |  |
| 37. AIR CONDITION               |  | 38. AUDIO/VIDEO    |  |
| 39. LIGHTS                      |  | 40. MISCELLANEOUS  |  |
| 41. MAINTENANCE                 |  | 42. INSPECTION     |  |
| 43. TIRE                        |  | 44. WASH/WAX       |  |
| 45. AIR CONDITION               |  | 46. AUDIO/VIDEO    |  |
| 47. LIGHTS                      |  | 48. MISCELLANEOUS  |  |
| 49. MAINTENANCE                 |  | 50. INSPECTION     |  |
| 51. TIRE                        |  | 52. WASH/WAX       |  |
| 53. AIR CONDITION               |  | 54. AUDIO/VIDEO    |  |
| 55. LIGHTS                      |  | 56. MISCELLANEOUS  |  |
| 57. MAINTENANCE                 |  | 58. INSPECTION     |  |
| 59. TIRE                        |  | 60. WASH/WAX       |  |
| 61. AIR CONDITION               |  | 62. AUDIO/VIDEO    |  |
| 63. LIGHTS                      |  | 64. MISCELLANEOUS  |  |
| 65. MAINTENANCE                 |  | 66. INSPECTION     |  |
| 67. TIRE                        |  | 68. WASH/WAX       |  |
| 69. AIR CONDITION               |  | 70. AUDIO/VIDEO    |  |
| 71. LIGHTS                      |  | 72. MISCELLANEOUS  |  |
| 73. MAINTENANCE                 |  | 74. INSPECTION     |  |
| 75. TIRE                        |  | 76. WASH/WAX       |  |
| 77. AIR CONDITION               |  | 78. AUDIO/VIDEO    |  |
| 79. LIGHTS                      |  | 80. MISCELLANEOUS  |  |
| 81. MAINTENANCE                 |  | 82. INSPECTION     |  |
| 83. TIRE                        |  | 84. WASH/WAX       |  |
| 85. AIR CONDITION               |  | 86. AUDIO/VIDEO    |  |
| 87. LIGHTS                      |  | 88. MISCELLANEOUS  |  |
| 89. MAINTENANCE                 |  | 90. INSPECTION     |  |
| 91. TIRE                        |  | 92. WASH/WAX       |  |
| 93. AIR CONDITION               |  | 94. AUDIO/VIDEO    |  |
| 95. LIGHTS                      |  | 96. MISCELLANEOUS  |  |
| 97. MAINTENANCE                 |  | 98. INSPECTION     |  |
| 99. TIRE                        |  | 100. WASH/WAX      |  |
| 101. AIR CONDITION              |  | 102. AUDIO/VIDEO   |  |
| 103. LIGHTS                     |  | 104. MISCELLANEOUS |  |
| 105. MAINTENANCE                |  | 106. INSPECTION    |  |
| 107. TIRE                       |  | 108. WASH/WAX      |  |
| 109. AIR CONDITION              |  | 110. AUDIO/VIDEO   |  |
| 111. LIGHTS                     |  | 112. MISCELLANEOUS |  |
| 113. MAINTENANCE                |  | 114. INSPECTION    |  |
| 115. TIRE                       |  | 116. WASH/WAX      |  |
| 117. AIR CONDITION              |  | 118. AUDIO/VIDEO   |  |
| 119. LIGHTS                     |  | 120. MISCELLANEOUS |  |
| 121. MAINTENANCE                |  | 122. INSPECTION    |  |
| 123. TIRE                       |  | 124. WASH/WAX      |  |
| 125. AIR CONDITION              |  | 126. AUDIO/VIDEO   |  |
| 127. LIGHTS                     |  | 128. MISCELLANEOUS |  |
| 129. MAINTENANCE                |  | 130. INSPECTION    |  |
| 131. TIRE                       |  | 132. WASH/WAX      |  |
| 133. AIR CONDITION              |  | 134. AUDIO/VIDEO   |  |
| 135. LIGHTS                     |  | 136. MISCELLANEOUS |  |
| 137. MAINTENANCE                |  | 138. INSPECTION    |  |
| 139. TIRE                       |  | 140. WASH/WAX      |  |
| 141. AIR CONDITION              |  | 142. AUDIO/VIDEO   |  |
| 143. LIGHTS                     |  | 144. MISCELLANEOUS |  |
| 145. MAINTENANCE                |  | 146. INSPECTION    |  |
| 147. TIRE                       |  | 148. WASH/WAX      |  |
| 149. AIR CONDITION              |  | 150. AUDIO/VIDEO   |  |
| 151. LIGHTS                     |  | 152. MISCELLANEOUS |  |
| 153. MAINTENANCE                |  | 154. INSPECTION    |  |
| 155. TIRE                       |  | 156. WASH/WAX      |  |
| 157. AIR CONDITION              |  | 158. AUDIO/VIDEO   |  |
| 159. LIGHTS                     |  | 160. MISCELLANEOUS |  |
| 161. MAINTENANCE                |  | 162. INSPECTION    |  |
| 163. TIRE                       |  | 164. WASH/WAX      |  |
| 165. AIR CONDITION              |  | 166. AUDIO/VIDEO   |  |
| 167. LIGHTS                     |  | 168. MISCELLANEOUS |  |
| 169. MAINTENANCE                |  | 170. INSPECTION    |  |
| 171. TIRE                       |  | 172. WASH/WAX      |  |
| 173. AIR CONDITION              |  | 174. AUDIO/VIDEO   |  |
| 175. LIGHTS                     |  | 176. MISCELLANEOUS |  |
| 177. MAINTENANCE                |  | 178. INSPECTION    |  |
| 179. TIRE                       |  | 180. WASH/WAX      |  |
| 181. AIR CONDITION              |  | 182. AUDIO/VIDEO   |  |
| 183. LIGHTS                     |  | 184. MISCELLANEOUS |  |
| 185. MAINTENANCE                |  | 186. INSPECTION    |  |
| 187. TIRE                       |  | 188. WASH/WAX      |  |
| 189. AIR CONDITION              |  | 190. AUDIO/VIDEO   |  |
| 191. LIGHTS                     |  | 192. MISCELLANEOUS |  |
| 193. MAINTENANCE                |  | 194. INSPECTION    |  |
| 195. TIRE                       |  | 196. WASH/WAX      |  |
| 197. AIR CONDITION              |  | 198. AUDIO/VIDEO   |  |
| 199. LIGHTS                     |  | 200. MISCELLANEOUS |  |
| 201. MAINTENANCE                |  | 202. INSPECTION    |  |
| 203. TIRE                       |  | 204. WASH/WAX      |  |
| 205. AIR CONDITION              |  | 206. AUDIO/VIDEO   |  |
| 207. LIGHTS                     |  | 208. MISCELLANEOUS |  |
| 209. MAINTENANCE                |  | 210. INS           |  |

Diagnostic report page 1

[illegible]

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JTDPYGJ1S00976829



## CONDITION REPORT



Report No:

2017303166

DATE

25/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JTDPYGJ1S00976829



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JTDPYGJ1S00976829



## CONDITION REPORT



Report No:

2017303166

DATE

25/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JTD037A



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026



C • Pillar Right



Hood Lining

| Brake test                 |             |         |              |         |    |
|----------------------------|-------------|---------|--------------|---------|----|
|                            | Brake force |         | Difference   |         |    |
|                            | left        | right   |              |         |    |
| Front axle                 | 2,87 kN     | 2,99 kN | 3 %          |         | St |
| Parking brake              | 1,95 kN     | 2,13 kN | 11 %         |         | Ps |
| Rear axle                  | 1,40 kN     | 0,71 kN | 49 %         |         | Rs |
| Front evaluation in auto   |             |         |              |         | LS |
| Deceleration service brake |             | 50 %    |              |         | DS |
| Deceleration parking brake |             | 29 %    |              |         | ST |
|                            |             |         | Total weight | 1462 kg | PF |

Service Brake Performance Rear Axle



Rear Fender Right



Rear Fender Left



Bonnet

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JTDPYGJ1S00976829



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026



Windscreen




Boot Lid / Hatch door



Water level



Tyre Front Right



Tyre Front Left



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JTDPGJ1S00976829



## CONDITION REPORT



Report No:  
2017303166  
DATE  
25/09/2026



Roof

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: JTDPYGJ1S00976829