



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/05/2025		M57 Pretoria Road - 1619
Inspection Date	09/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	CHEVROLET	Registration Number	HZC416MP
Model	CRUZE 1.6 L [2012-2013]	Register Number	
VIN	KL1JF69E9DK027976	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model	2012	Paint Finish	M - METALLIC
Km Reading	180,110 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Radiator Water Leak	Repair
Water level Insufficient	Repair
Switch Electrical Window Winder front left Defective	Repair
Switch Electrical Window Winder front right Defective	Repair
Switch Electrical Window Winder rear left Defective	Repair
Switch Electrical Window Winder rear right Defective	Repair
Tail Light Left Damaged	Replace
Wiring connections Defective	Repair
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Torn / Cut	Repair
Door Handle Rear Right Damaged	Repair
Gear Lever Dust Boot Torn / Cut	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Dented	Repair
C • Pillar Left Paintwork • Scratched	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Damage	Repair Way
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Residual Traces of Repair	Repair
Sill Panel Left Residual Traces of Repair	Repair
Sill Panel Right Residual Traces of Repair	Repair
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	Repair
Tyre Front Right Smooth	Replace
Tyre Rear Left Excessive Wear & Tear	Replace
Tyre Rear Right Smooth	Replace
Rim Front Right Dented	Repair
Rim Rear Left Damaged	Repair
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Radiator Cradle Damaged	Replace
Engine Performance Insufficient	Repair
Engine Noise Excessive	Repair
Front tyre size differs	Replace
Rear tyre size differs	Replace
Vehicle electronics malfunction	Repair
Multiple warning lights illuminated	Repair
Body exterior	Signs of spray work done on some body panels
Body exterior	Residual traces of poor repair on most body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.7	2.3	-	
Rear	1.9	2.2	-	
Emergency / Parking	1.4	1.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/60R16	92H	Goodyear	Assurance	V	4619	1 mm
Front Right	205/55R16	91H	Michelin	Energy	V	0000	0 mm
Rear Left	205/55R16	91W	Continental	Contact	V	0000	2 mm
Rear Right	215/55R16	95H	Continental	Contact	V	4308	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025**Diagnostic**

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BODY CONTROL MODULE	B1517:03	BATTERY VOLTAGE LOW VOLTAGE	
2	ENGINE CONTROL MODULE	P0520:00	ENGINE OIL PRESSURE SWITCH CIRCUIT	
3	ENGINE CONTROL MODULE	P0597:00	ENGINE COOLANT THERMOMETER HEATER CONTROL CIRCUIT	

Inspection Conditions

No Test Drive
Vehicle doesn't start
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



Multiple warning lights illumi



ABS warning lights illuminated



INTERIOR (FRONT DRIVER DOOR)



Manual

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Rear end



No sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Oil cap and dipstick



ENGINE 1



ENGINE 2



CHASSIS



R/F fender liner missing



R/F fender liner missing

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025


Expansion bottle




VIN PLATE OR STICKER




No license disc



SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976




CONDITION REPORT


Report No: 2016871664

DATE
09/05/2025


DIAGNOSTIC REPORT PAGE 3




DIAGNOSTIC REPORT PAGE 4




DIAGNOSTIC REPORT PAGE 5



DIAGNOSTIC REPORT PAGE 6



DIAGNOSTIC REPORT PAGE 7



DIAGNOSTIC REPORT PAGE 8


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976




CONDITION REPORT


Report No: 2016871664

DATE
09/05/2025


DIAGNOSTIC REPORT PAGE 9




DIAGNOSTIC REPORT PAGE 10




DIAGNOSTIC REPORT PAGE 11



DIAGNOSTIC REPORT PAGE 12



DIAGNOSTIC REPORT PAGE 13



DIAGNOSTIC REPORT PAGE 14


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976




CONDITION REPORT


Report No: 2016871664

DATE
09/05/2025

DIAGNOSTIC REPORT PAGE 15



DIAGNOSTIC REPORT PAGE 16



Front Fender Right



Door Front Right



Door Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Switch Electrical Window Winder front right



Seat Front Right



Seat Front Right



Seat Front Left



Gear Lever Dust Boot



Wiring connections

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Wiring connections



Door Front Right



Sill Panel Right



Sill Panel Right



Sill Panel Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Door Handle Rear Right



Tail Light Left



Tail Light Left



Boot Lid / Hatch door



Boot Lid / Hatch door



C • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Rear Fender Left



Door Rear Left



Door Front Left



Side Mirror Left



Seat Rear



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025


Front Fender Left



Bonnet



Bonnet



Service Brake Performance Front Axle



Engine Wiring



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Engine Wiring



Engine Wiring



Engine Wiring



Engine Wiring



Water level



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Front Bumper



Front Bumper



Front Bumper



Front Bumper



Grill



Bolt(s) / Nut(s) Front Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Rim Rear Left



Rear bumper



Rear bumper



Rear bumper



Rear bumper



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Radiator Cradle



Radiator Cradle



Rim Front Right



Engine



Engine



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT


Report No: 2016871664

DATE
09/05/2025

Sill Panel Left



Sill Panel Left



Tyre Rear Left



Tyre Rear Right



Sill Panel Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976



CONDITION REPORT

Report No: 2016871664

DATE
09/05/2025

Sill Panel Right



Switch Electrical Window Winder front left



Switch Electrical Window Winder rear left



Switch Electrical Window Winder rear right



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1JF69E9DK027976