

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 26/01/2024 | | M57 Pretoria Road - 1619 |
| Inspection Date | 26/01/2024 | | Kempton Park - GT |

Vehicle Data

| | | | |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | HYUNDAI | Registration Number | HJ83HZGP |
| Model | ACCENT | Register Number | |
| VIN | KMHCT41DLJU404664 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 4 | License Expiry Date | 26/01/2024 |
| Color | GREY | Power / Displacement | |
| Year Model | | Paint Finish | M - METALLIC |
| Km Reading | 376,606 KM | Fuel | PETROL |
| Cab / Body Type | SEDAN | Transmission | MANUAL |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

| Damage | Repair Way |
|---|------------|
| Hooter Defective | Repair |
| Window Winder rear left Missing | Replace |
| Number Plate Rear Missing | Replace |
| Side Mirror Left Paintwork • Scratched | Repair |
| Side Mirror Right Paintwork • Scratched | Repair |
| Front Bumper Damaged | Repair |
| Bonnet Paintwork • Scratched | Repair |
| Front Fender Left Paintwork • Scratched | Repair |
| Rear Fender Left Paintwork • Scratched | Repair |
| Door Front Left Paintwork • Scratched | Repair |
| Door Front Right Dented | Repair |
| Door Rear Left Dented | Repair |
| Door Rear Right Paintwork • Scratched | Repair |
| Boot Lid / Hatch door Dented | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Sill Panel Left Dented | Repair |
| Sill Panel Right Dented | Repair |
| Windscreen Cracked | Replace |
| Wheel bearing Front Left Free play | Replace |
| Tyre Front Left Damaged | Replace |
| Tyre Rear Right Damaged | Replace |
| Spare Tyre Smooth | Replace |
| CV Joint(s) Boot(s) Front Left (inner/outer) Defective | Repair |
| CV Joint(s) Boot(s) Front Right (inner/outer) Defective | Repair |
| Radiator Cradle Dented | Repair |
| No license dice | Replace |
| L/F fender line missing | Replace |
| R/F fender line damage | Replace |
| Airbag light on | Repair |

Brakes

Brake Test Results

| | Left | Right | Axle Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | 2.6 | 3.0 | - | |
| Rear | 2.3 | 2.4 | - | |
| Emergency / Parking | 1.5 | 1.5 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|----------|-------|-----------------|------------------|
| Front Left | 185/60R14 | 82H | Michelin | Energy | V | 3017 | 0 mm |
| Front Right | 185/65R14 | 85H | Nexen | N priz | V | 4722 | 1 mm |
| Rear Left | 185/60R14 | 82H | Davanti | Dx390 | V | 0820 | 1 mm |
| Rear Right | 185/60R14 | 82H | Yokohama | A539 | V | 0513 | 0 mm |
| Spare | 175/65R14 | 82H | Neolin | Neogreen | V | 2621 | 0 mm |

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ?ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Vehicle got minor scratches, stone chips and dents on some body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)




INTERIOR (FRONT DRIVER DOOR)



Manual



Coolant bottle



Oil cap and dipstick



Spare wheel



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



ENGINE 2

VIN: KMHCT41DLJU404664

7 / 13

VIN: KMHCT41DLJU404664
8 / 13



CHASSIS




ENGINE 1




VIN PLATE OR STICKER



LICENSE DISC MISSING




SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1

VIN: KMHCT41DLJU404664

9 / 13




DIAGNOSTIC REPORT PAGE 2




VIN: KMHCT41DLJU404664
10 / 13


Windscreen



Water level



Window Winder rear left



Spare Tyre



Number Plate Rear

VIN: KMHCT41DLJU404664

11 / 13



Side Mirror Right



Front Bumper

VIN: KMHCT41DLJU404664
12 / 13



Front Bumper



Front Bumper



Front Bumper



Front Fender Left

VIN: KMHCT41DLJU404664

13 / 13



Sill Panel Left



Sill Panel Right



Door Front Right



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right



Tyre Front Left



Tyre Rear Right



Wheel bearing Front Left



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Radiator Cradle



Bonnet



Hooter



CONDITION REPORT

Report No: 2016244506

DATE
26/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za