



CONDITION REPORT



Report No:

2017303392

DATE

25/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/09/2026		M57 Pretoria Road - 1619
Inspection Date	25/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	FL40TDGP
Model	ACCENT 1.6 FLUID 6-SP [2013-2021]	Register Number	
VIN	KMHCU41DLGU069208	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/10/2025
Color	WHITE	Power / Displacement	
Year Model	2016	Paint Finish	TWO COAT UNI
Km Reading	180,881 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:

2017303392

DATE

25/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Tail Light Left Damaged	Replace
Tail Light Right Cracked	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Hood Lining Dirty	Repair
Door Panel Rear Left Damaged	Repair
Door Panel Rear Right Damaged	Repair
Door Sealing Rubber Front Left Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Clutch Pedal Rubber Damaged	Replace
Brake Pedal Rubber Torn / Cut	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
C • Pillar Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Right Paintwork • Scratched	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Dented	Repair
Roof Dented	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Tyre Rear Left Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Chassis Dented	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.14	2.66	-	
Rear	2.63	3.0	-	
Emergency / Parking	1.76	1.94	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/50 R16	84V	Yokohama	Bluearth	V	1424	5 mm
Front Right	195/50 R16	84V	Yokohama	Bluearth	V	1424	5 mm
Rear Left	195/50 R16	84H	Kumho	Ecowing	V	1218	2 mm
Rear Right	195/50 R16	84H	Kumho	Ecowing	V	4419	1 mm
Spare	195/50 R16	84H	Kumho	Ecowing	V	4419	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0335	CRANKSHAFT POSITION(CKP) SENSOR'A' CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Dents and scratches on body panels
Tyres and Rims: Spare Wheel deflated.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:

Report No.
2017303392

DATE _____

25/09/2026

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:

2017303392

DATE

25/09/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Spare Wheel Accessories



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208




CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Water level



Water level



Seat Front Right



Seat Front Right



Door Sealing Rubber Front Right



Door Sealing Rubber Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



C • Pillar Left



Door Panel Rear Left



Door Sealing Rubber Front Left



Seat Front Left



Side Mirror Left



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Rear Fender Right



Door Front Right



Door Front Right



Rear bumper



Rear bumper



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Boot Lid / Hatch Door Rubbers



Tail Light Right



Tail Light Left



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Control Arm Bush(es) Front Axle Right



Front Fender Right / Inner Tray



Front Bumper



Front Bumper



Front Bumper



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Control Arm Bush(es) Front Axle Left



Sill Panel Left



Rim Rear Left



Bolt(s) / Nut(s) Rear Wheel Left



Tyre Rear Left



CV Joint(s) Boot(s) Front Right (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Engine



CV Joint(s) Boot(s) Front Right (inner/outer)



Chassis



Chassis



Mounting Rubber(s) Rear Axle Left



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208



CONDITION REPORT



Report No:
2017303392
DATE
25/09/2026



Clutch Pedal Rubber




Brake Pedal Rubber



Steering Wheel Trim



Hood Lining



Center Console / Cubbyhole + Lid



Door Panel Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DLGU069208