



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	
Requested Date	12/08/2024		
Inspection Date	12/08/2024	M57 Pretoria Road - 1619 Kempton Park - GT	

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	FH64YBGP
Model	ACCENT	Register Number	
VIN	KMHCU41DMHU135734	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/06/2025
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	268,548 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Defective	Replace
Air cleaner Defective	Replace
Bonnet safety caps Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Switch Electrical Window Winder front left Damaged	Replace
Windscreen Wiper Damaged	Replace
Air Conditioner Insufficient	Replace
Tail Light Left Damaged	Replace
Fog Light Front Left Defective	Replace
Number Plate Light Left Defective	Replace
Number Plate Light Right Defective	Replace
Headlight Left Defective	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Defective	Repair
Sun Visor Left Dirty	Repair
Sun Visor Right Dirty	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Left Torn / Cut	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Left Torn / Cut	Replace
Boot Carpet Damaged	Repair
Steering Wheel Trim Defective	Repair
Side Mirror Left Residual Traces of Repair	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Replace
Grill Cracked	Replace
Bonnet Paintwork • Flaking	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCU41DMHU135734

1 / 24



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Damage	Repair Way
Bonnet slam plate (Shock tower/ Inner tray) Cracked	Repair
B • Pillar Left Dented	Repair
C • Pillar Left Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Residual Traces of Repair	Repair
Door Front Right Damaged	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Dented	Repair
Doorstopper Rear Left Defective	Replace
Doorstopper Rear Right Defective	Replace
Boot Lid / Hatch door Paintwork • Scratched	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Paintwork • Scratched	Repair
Rocker Panel Right Dented	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Brake Pad/Shoe 2. Axle left Defective	Replace
Brake Pad/Shoe 2. Axle right Defective	Replace
Tie Rod right Defective	Replace
Stabilizer Mounting Front Right Damaged	Replace
Wheel bearing Front Left Loose / Excessive Play	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Ball Joint(s) Front Axle Left Welded	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Spare Tyre Torn / Cut	Replace
Rim Front Left Damaged	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Dented	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Repair
Silencer Defective	Repair
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair
Fuel Tank Dented	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Engine Performance Insufficient	Repair
Gear Selections Slippy Hesitation	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Axle and suspension	Front and rear suspension noisy
Engine	Engine bay dirty and battery loose
Engine	Injector rail insulation cover damaged
Undercarriage	Vehicle undercarriage dirty
Tyres and rims	Rear left and right tyre sizes different
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Residual traces of repair on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Undercarriage	Signs of engine and gearbox mounting rubbers worn



CONDITION REPORT

VIN: KMHCU41DMH135734
Report No: 2016488292
2 / 24
DATE
12/08/2024

Brakes
Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.06	2.71	-	
Rear	2.38	2.5	-	
Emergency / Parking	1.28	1.58	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292
VIN: KMHCU41DMHU135734
DATE
12/08/2024

Tyres and Rims
Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65 R14	86H	Radar	RPX-800	V	2322	0 mm
Front Right	175/65 R14	86H	Radar	RPX-800	V	3721	0 mm
Rear Left	185/60 R14	82H	Goodyear	Efficient	V	1919	5 mm
Rear Right	175/65 R14	86T	Lanvigator	Catchgrip	V	1819	1 mm
Spare	185/60 R14	82H	Firestone	Multihawk	V	3010	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0268	CYLINDER 3 INJECTOR CIRCUIT HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024
4/24

Vehicle Data				Engine Data			
Make/Model	Chevrolet	Year	2016	Engine No.	140000000	Engine Type	Gasoline
Chassis No.	12345678	Registration	12345678	Transmission	Automatic	Drive Type	Front Wheel Drive
Color	White	Engine Oil	5W-30	Oil Level	OK	Oil Pressure	OK
Engine Oil	5W-30	Oil Level	OK	Oil Pressure	OK	Oil Temperature	OK
Brake Fluid	DOT 4	Brake Level	OK	Brake Pressure	OK	Brake Temperature	OK
Shock Absorbers	Front: OK, Rear: OK	Shock Level	OK	Shock Pressure	OK	Shock Temperature	OK
Steering	OK	Steering Level	OK	Steering Pressure	OK	Steering Temperature	OK
Wheels/Tires	Front: OK, Rear: OK	Wheel Level	OK	Wheel Pressure	OK	Wheel Temperature	OK
Exhaust	OK	Exhaust Level	OK	Exhaust Pressure	OK	Exhaust Temperature	OK
Lighting	OK	Lighting Level	OK	Lighting Pressure	OK	Lighting Temperature	OK
Electrical	OK	Electrical Level	OK	Electrical Pressure	OK	Electrical Temperature	OK
Interior	OK	Interior Level	OK	Interior Pressure	OK	Interior Temperature	OK
Exterior	OK	Exterior Level	OK	Exterior Pressure	OK	Exterior Temperature	OK
Overall	OK	Overall Level	OK	Overall Pressure	OK	Overall Temperature	OK

Brake and shock absorber report

Vehicle Data				Engine Data			
Make/Model	Chevrolet	Year	2016	Engine No.	140000000	Engine Type	Gasoline
Chassis No.	12345678	Registration	12345678	Transmission	Automatic	Drive Type	Front Wheel Drive
Color	White	Engine Oil	5W-30	Oil Level	OK	Oil Pressure	OK
Engine Oil	5W-30	Oil Level	OK	Oil Pressure	OK	Oil Temperature	OK
Brake Fluid	DOT 4	Brake Level	OK	Brake Pressure	OK	Brake Temperature	OK
Shock Absorbers	Front: OK, Rear: OK	Shock Level	OK	Shock Pressure	OK	Shock Temperature	OK
Steering	OK	Steering Level	OK	Steering Pressure	OK	Steering Temperature	OK
Wheels/Tires	Front: OK, Rear: OK	Wheel Level	OK	Wheel Pressure	OK	Wheel Temperature	OK
Exhaust	OK	Exhaust Level	OK	Exhaust Pressure	OK	Exhaust Temperature	OK
Lighting	OK	Lighting Level	OK	Lighting Pressure	OK	Lighting Temperature	OK
Electrical	OK	Electrical Level	OK	Electrical Pressure	OK	Electrical Temperature	OK
Interior	OK	Interior Level	OK	Interior Pressure	OK	Interior Temperature	OK
Exterior	OK	Exterior Level	OK	Exterior Pressure	OK	Exterior Temperature	OK
Overall	OK	Overall Level	OK	Overall Pressure	OK	Overall Temperature	OK

Diagnostic report page 1

Vehicle Data				Engine Data			
Make/Model	Chevrolet	Year	2016	Engine No.	140000000	Engine Type	Gasoline
Chassis No.	12345678	Registration	12345678	Transmission	Automatic	Drive Type	Front Wheel Drive
Color	White	Engine Oil	5W-30	Oil Level	OK	Oil Pressure	OK
Engine Oil	5W-30	Oil Level	OK	Oil Pressure	OK	Oil Temperature	OK
Brake Fluid	DOT 4	Brake Level	OK	Brake Pressure	OK	Brake Temperature	OK
Shock Absorbers	Front: OK, Rear: OK	Shock Level	OK	Shock Pressure	OK	Shock Temperature	OK
Steering	OK	Steering Level	OK	Steering Pressure	OK	Steering Temperature	OK
Wheels/Tires	Front: OK, Rear: OK	Wheel Level	OK	Wheel Pressure	OK	Wheel Temperature	OK
Exhaust	OK	Exhaust Level	OK	Exhaust Pressure	OK	Exhaust Temperature	OK
Lighting	OK	Lighting Level	OK	Lighting Pressure	OK	Lighting Temperature	OK
Electrical	OK	Electrical Level	OK	Electrical Pressure	OK	Electrical Temperature	OK
Interior	OK	Interior Level	OK	Interior Pressure	OK	Interior Temperature	OK
Exterior	OK	Exterior Level	OK	Exterior Pressure	OK	Exterior Temperature	OK
Overall	OK	Overall Level	OK	Overall Pressure	OK	Overall Temperature	OK

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
5 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734

6 / 24



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
7 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
9 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Injector rail insulation cover

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
11 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Oil cap and dipstick



Steering Wheel Trim

VIN: KMHCU41DMHU135734
12 / 24

Sun Visor Right



Sun Visor Left



Hood Lining



Center Console / Cubbyhole + Lid



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
13 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024



Windscreen Wiper




Windscreen


VIN: MHCJ41DMHU135734
14 / 24



Air Conditioner



Seat Front Right



Door Sealing Rubber Front Right



Sill Panel Right



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
15 / 24


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024



Doorstopper Rear Right



Seat Rear

ID: MHU135734
16 / 24



Rear Fender Right



Door Rear Right



Door Front Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
17 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024



Front Fender Right



Front Bumper

VIN: KMHCU41DMHU135734

18 / 24



Front Bumper



Bonnet



Front Fender Left



Side Mirror Left



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
19 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Door Front Left



Door Rear Left



Rear Fender Left



Seat Front Left



Door Sealing Rubber Front Left



B • Pillar Left



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
21 / 24

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024



Doorstopper Rear Left



C • Pillar Left



Door Sealing Rubber Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

VIN: KMHCU41DMHU135734
23 / 24



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024



Tail Light Left



Roof



Boot Lid / Hatch Door Rubbers



Spare Tyre

VIN: KMHCU41DMHU135734
24 / 24



Inner Boot Floor Pan and Spare Wheel Well



Boot Carpet



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Engine



Water level



Engine Wiring



Air cleaner



Bonnet slam plate (Shock tower/ Inner tray)



Headlight Left



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Rim Front Right



Front Fender Right / Inner Tray



Control Arm Bush(es) Front Axle Right



Grill



Fog Light Front Left



Front Fender Left / Inner Tray



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Rim Front Left



Wheel bearing Front Left



Sill Panel Left



Rim Rear Left



Number Plate Light Right



Number Plate Light Left



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Rear bumper



Rim Rear Right



Rocker Panel Right



Sub Frame



Gearbox



Tyre Front Left



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Tyre Front Right



CV Joint(s) Boot(s) Front Left (inner/outer)



Ball Joint(s) Front Axle Left



Air cleaner



CV Joint(s) Boot(s) Front Right (inner/outer)



Chassis



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

CV Joint(s) Boot(s) Front Right (inner/outer)




Stabilizer Mounting Front Right



Tie Rod right



Engine



Chassis



Silencer



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Fuel Tank



Rim Rear Right



Inner Boot Floor Pan and Spare Wheel Well



Brake Pad/Shoe 2. Axle left



Brake Pad/Shoe 2. Axle right



Belly plates



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

Water level



Bonnet safety caps



Switch Electrical Window Winder front left



Center Console / Cubbyhole + Lid



CONDITION REPORT

Report No: 2016488292

DATE
12/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za