

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/05/2025		M57 Pretoria Road - 1619
Inspection Date	27/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	LH88LXGP
Model	TUCSON	Register Number	
VIN	KMHJ2813LHU286662	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	281,641 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Switch Electrical Window Winder rear right Defective	Repair
Seat Front Right Torn / Cut	Repair
Interior Mirror Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Flaking	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle right Worn	Replace
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	Repair
Steering Rack Boot Right Leak	Replace
Stabilizer Mounting Rear Right Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHJ2813LHU286662

Damage	Repair Way
Tyre Front Left Smooth	Replace
Tyre Front Right Smooth	Replace
Spare Tyre Smooth	Replace
Rim Front Left Dented	Repair
Rim Front Right Dented	Repair
Rim Rear Left Dented	Repair
Main Beam Left Damaged	Repair
Engine to silencer pipe Leak	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Radio electronics malfunction.	Repair
Boot electric fault does not open	Repair
Body exterior	Residual traces of poor repair on some body panel
Body exterior	Signs of spray work done on some body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.5	2.8	-	
Rear	1.9	1.6	-	
Emergency / Parking	0.8	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R17	96H	Lanvigator	Performance	V	0221	0 mm
Front Right	215/60R17	100H	Radar	RPax	V	3221	0 mm
Rear Left	215/55R17	94V	Bridgestone	Turanza	V	1121	5 mm
Rear Right	215/55R17	94V	Bridgestone	Turanza	V		2 mm
Spare	215/60R17	100H	Radar	RPX	V	///////	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIRBAG	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS

Concluding Remarks

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHJ2813LHU286662

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT




90 DEGREE LEFT



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



Expansion bottle



Oil cap and dipstick



R/F fender liner missing



Rear end



ENGINE 1



CHASSIS




ENGINE 2



VIN PLATE OR STICKER




LICENSE DISC



SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



Interior Mirror



Seat Front Right



Front Fender Right



Door Front Right



Door Rear Right



Rear bumper



Rear bumper



Rear bumper



Door Rear Left



Rear Fender Left



Side Mirror Left



Bonnet



Bonnet



Front Bumper



Front Bumper



Front Bumper



Windscreen



Water level



Engine Wiring

Brake Test		Left	Right	Total
1. Press. (kPa)		0.25	0.27	0.52
2. Pedal stroke (mm)		1.0	1.0	2.0
3. Pedal force (N)		1.0	1.0	2.0
4. Pedal travel (mm)		1.0	1.0	2.0
5. Pedal force (N)		1.0	1.0	2.0
6. Pedal travel (mm)		1.0	1.0	2.0
7. Pedal force (N)		1.0	1.0	2.0
8. Pedal travel (mm)		1.0	1.0	2.0
9. Pedal force (N)		1.0	1.0	2.0
10. Pedal travel (mm)		1.0	1.0	2.0
11. Pedal force (N)		1.0	1.0	2.0
12. Pedal travel (mm)		1.0	1.0	2.0
13. Pedal force (N)		1.0	1.0	2.0
14. Pedal travel (mm)		1.0	1.0	2.0
15. Pedal force (N)		1.0	1.0	2.0
16. Pedal travel (mm)		1.0	1.0	2.0
17. Pedal force (N)		1.0	1.0	2.0
18. Pedal travel (mm)		1.0	1.0	2.0
19. Pedal force (N)		1.0	1.0	2.0
20. Pedal travel (mm)		1.0	1.0	2.0

Service Brake Performance Front Axle



Brake disc 1. Axle right



Tyre Front Right



Front Bumper



Tyre Front Left



Rim Front Left



Rim Front Right



Radiator Cradle



Radiator Cradle



Radiator Cradle



Radiator Cradle



Radiator Cradle



Main Beam Left



Engine



Engine



Engine



Gearbox



Gearbox



CV Joint(s) Boot(s) Front Right (inner/outer)



Steering Rack Boot Right



Rim Rear Left



Rim Rear Left



Stabilizer Mounting Rear Right



Stabilizer Mounting Rear Right



Engine to silencer pipe



Spare Tyre



Switch Electrical Window Winder rear right



Switch Electrical Window Winder rear right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHJ2813LHU286662