



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	04/04/2025		M57 Pretoria Road - 1619
Inspection Date	04/04/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	KDJ061MP
Model	H-1 2.4 GLS 9-S BUS [2009-2016]	Register Number	
VIN	KMHW81RLAU234212	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2025
Color	WHITE	Power / Displacement	
Year Model	2010	Paint Finish	TWO COAT UNI
Km Reading	260,267 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Hoses Damaged	Repair
Fan Belt Damaged	Replace
Engine Management Lights Set	Repair
Seat Front Left Worn	Repair
Seat Front Right Worn	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Sun Visor Right Damaged	Replace
Door Handle Rear Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHW81RLAU234212



CONDITION REPORT

Report No: 2016828308

 DATE
04/04/2025

Damage	Repair Way
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Window Rear Door Left Damaged	Replace
Sealing Window Rear Door Left Damaged	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Steering box Leak	Repair
Steering Rack Boot Left Damaged	Replace
Shock Absorber Front Right Worn	Replace
Stabilizer Mounting Front Left Damaged	Replace
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Gearbox Oil Leak	Repair
Center Prop Shaft Rubber(s) Damaged	Replace
Steering Insufficient	Repair
Gear Selections Insufficient	Repair
Rear tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.8	4.19	-	
Rear	0.05	5.79	-	
Emergency / Parking	2.94	1.52	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/75R16	108R	Dunlop	Sp	V	4723	2 mm
Front Right	195/75R16	108R	Dunlop	Radial	V	4723	3 mm
Rear Left	195/75R16	105R	Rapid	Radial	V	1024	4 mm
Rear Right	215/65R16	98H	Kumho	Radial	V	1709	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG	P1693	IN MOBILIZER TRANSPONDER ERROR	

Inspection Conditions

No Test Drive
 Rain at time of inspection
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

 DATE
 04/04/2025

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Battery loose.

Interior: driver side seat loose. vehicle interior in poor condition.

Body • Exterior: Minor dents and scratches to some body panels. Signs of stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Vehicle body in poor condition.

Axle and Suspension: excessive noise from front and rear suspension.

Road Test: vehicle has no power steering. manual gearbox struggles to select gear.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212




CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Brake test



Diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



Hoses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Engine



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Front Fender Right



Door Front Right




Door Rear Right



Door Handle Rear Right



Window Rear Door Left



Sealing Window Rear Door Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Windscreen



Fan Belt



Seat Front Right



Seat Front Left



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Seat Rear (2. Row)



Sun Visor Right



Sun Visor Right



Engine Management Lights



Steering box



Steering box

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT

Report No: 2016828308

DATE
04/04/2025

Steering box



Steering Rack Boot Left



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right



Shock Absorber Front Right



Center Prop Shaft Rubber(s)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212



CONDITION REPORT


Report No: 2016828308

DATE
04/04/2025

Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Rear Wheel Right



Gearbox



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHWH81RLAU234212