



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	23/09/2026		M57 Pretoria Road - 1619
Inspection Date	23/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	KIA	Registration Number	JWH057MP
Model	PICANTO	Register Number	
VIN	KNAB2511MKT365271	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREEN	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	140,432 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:

2017302491

DATE

23/09/2026



Damage

Repair Way

Engine Management Lights Set
 Windscreen Wiper Damaged
 Tail Light Left Damaged
 Headlight Left Damaged
 Headlight Right Damaged
 Front Bumper Damaged
 Bonnet Damaged
 Front Fender Left Damaged
 Front Fender Right Damaged
 Rear Fender Left Damaged
 Rear Fender Right Damaged
 Door Front Left Damaged
 Door Front Right Damaged
 Door Rear Left Damaged
 Door Rear Right Damaged
 Boot Lid / Hatch door Damaged
 Rear bumper Defective
 Roof Damaged
 Windscreen Damaged
 Radiator Cradle Damaged

Repair
 Replace
 Replace
 Replace
 Replace
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Replace
 Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.63	2.4	-	
Rear	0.88	0.94	-	
Emergency / Parking	1.32	1.43	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	155/80R13	79T	Sailun	Radial	V	3824	1 mm
Front Right	155/80R13	79T	Sailun	Radial	V	3524	2 mm
Rear Left	155/80R13	79T	Sailun	Radial	V	3824	2 mm
Rear Right	155/80R13	79T	Sailun	Radial	V	3524	3 mm
Spare	T115/70D15	90M	Maxxis	Temporary	V	////	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG	P0202:00	CYLINDER 2 INJECTOR CIRCUIT OPEN	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: dipstick damaged. oil level could not be checked correctly. battery loose.

Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Signs of hail damage to some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:

2017302491

DATE

23/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:

2017302491

DATE

23/09/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Automatic.



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026



RR TYRE TREAD




RF TYRE TREAD



spare wheel.



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026




ENGINE 1




VIN PLATE OR STICKER



LICENSE DISC



BRAKE TEST REPORT



DIAGNOSTIC REPORT



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026




Windscreen Wiper



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026



Door Front Right



Rear Fender Right



Front Fender Right



Roof



Windscreen



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271



CONDITION REPORT



Report No:
2017302491
DATE
23/09/2026



Headlight Left



Tail Light Left



Radiator Cradle



Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511MKT365271