



CONDITION REPORT



Report No:

2017304207

DATE

28/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/09/2026		M57 Pretoria Road - 1619
Inspection Date	28/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	KIA	Registration Number	BF62DDZN
Model	RIO	Register Number	
VIN	KNADB512LL6390470	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2025
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	199,209 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Damage	Repair Way
Interior Lights Damaged	Replace
Tail Light Left Scratched	Repair
Tail Light Right Cracked	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
C • Pillar Left Defective	Repair
C • Pillar Right Defective	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Dull	Repair
Front Fender Left / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Replace
Rear Fender Right / Inner Tray Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Replace
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Damaged	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Brake Pad 1. Axle right Worn	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Right Dented	Repair
Rim Spare Wheel Dented	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Replace
Engine to silencer pipe Damaged	Repair
Silencer Damaged	Replace
Belly plates Damaged	Replace
Fuel Tank Damaged	Repair
Brakes Noisy	Repair
Rear bumper stiffener damaged	Replace
Rear left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.58	2.44	-	
Rear	2.32	2.54	-	
Emergency / Parking	1.55	1.74	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R15	88H	Roadstone	Eurovis	V	0000	3 mm
Front Right	185/60 R15	84H	Hankook	Kinergy	V	3122	3 mm
Rear Left	185/65 R15	88H	Goodride	Radial	V	2823	0 mm
Rear Right	185/60 R15	88H	Dunlop	Sp-Sport	V	2622	0 mm
Spare	185/60 R15	84H	Bridgestone	Ecopia	V	2516	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Non standard battery fitted to vehicle.
Lights: Front left and right headlight lenses faded
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Signs of impact damage to front and rear of vehicle.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Sign of hail damage on body panels.
Axle and Suspension: Front suspension faulty.
Road Test: Gear selection faulty.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report page 1

[illegible]

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:

2017304207

DATE

28/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:

2017304207

DATE

28/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Rear bumper stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Oil cap and dipstick



Steering Wheel Trim



Hood Lining



Interior Lights



Seat Front Right



Door Sealing Rubber Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT




Report No:

2017304207

DATE

28/09/2026



Seat Rear



Rear bumper



Rear bumper



Rear bumper



Tail Light Right



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Tyre Rear Left



Rear Fender Left / Inner Tray



Door Sealing Rubber Rear Left



C • Pillar Left



Seat Front Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Front Fender Left / Inner Tray



Tyre Front Right



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:

2017304207

DATE

28/09/2026



Side Mirror Right



Roof



Boot Lid / Hatch door



Spare Tyre



Rim Spare Wheel



C • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



C • Pillar Right



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Bonnet



Rim Front Right



Front Bumper



Front Bumper



Front Bumper



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Sill Panel Left



Rear Fender Right / Inner Tray



Belly plates



Sub Frame



Sub Frame



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Chassis



Chassis



Chassis



Engine to silencer pipe



Silencer



Fuel Tank

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Silencer



Tyre Rear Right



Chassis



Chassis



Tyre Rear Left



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Rear Fender Right / Inner Tray



Tyre Front Left



Brake Pad 1. Axle right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470



CONDITION REPORT



Report No:
2017304207
DATE
28/09/2026



Water level



Headlight Right



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB512LL6390470