



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	15/05/2025		M57 Pretoria Road - 1619
Inspection Date	15/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	KIA	Registration Number	KTF717NW
Model	RIO	Register Number	
VIN	KNADB514MN6602891	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	46,504 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Radiator Damaged	Repair
Windscreen Wiper Damaged	Replace
Headlight Left Defective	Repair
Steering Wheel Trim Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

Damage	Repair Way
Roof Damaged	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Chassis Damaged	Replace
Radiator Cradle Damaged	Replace
Engine Performance Insufficient	Repair
Engine Noise Excessive	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.55	2.42	-	
Rear	1.71	2.14	-	
Emergency / Parking	1.19	1.53	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Bridgestone	Radial	V	4519	0 mm
Front Right	185/65R15	88H	Nexen	Radial	V	1921	0 mm
Rear Left	185/65R15	88H	Nexen	Radial	V	1921	2 mm
Rear Right	185/65R15	88H	Nexen	Radial	V	1921	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P000A:00	CAMSOF POSITION A SLOW RESPONSE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 10 DTC'S AT TIME OF TESTING SEE DTC REPORT. Engine Compartment: foreign substance on oil filler cap. aircon condenser damaged. Sump damaged.

Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Vehicle body in poor condition. Repair work done to vehicle below standard.

Road Test: Vehicle struggles to idle and struggles to start.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891

[illegible]

Brake test.

	T.C. Milli Eğitim Bakanlığı Yükseköğretim Genel Müdürlüğü Yükseköğretim Kurulu Başkanlığı Yükseköğretim Kurulu Başkanlığı Yükseköğretim Kurulu Başkanlığı	Yükseköğretim Kurulu Başkanlığı Yükseköğretim Kurulu Başkanlığı Yükseköğretim Kurulu Başkanlığı Yükseköğretim Kurulu Başkanlığı Yükseköğretim Kurulu Başkanlığı
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM
ÖSYM	ÖSYM	ÖSYM

Diagnostic.

Page No.	Page No.	Page No.
1001-03	On-line position (ONP) / On-site position (OSP) creation (Bank / Service / Job)	History
1005-06	Cyberlink interface description	Setting
1007-08	Cyberlink interface description	Setting
1008-09	Cyberlink interface description	Setting
1009-10	Interface description	Setting
1010-11	Interface description	Setting
1011-12	Interface description	Setting
1012-13	Interface description	Setting
1013-14	Interface description	Setting
1014-15	Interface description	Setting
1015-16	Interface description	Setting
1016-17	Interface description	Setting
1017-18	Interface description	Setting
1018-19	Interface description	Setting
1019-20	Interface description	Setting
1020-21	Interface description	Setting
1021-22	Interface description	Setting
1022-23	Interface description	Setting
1023-24	Interface description	Setting
1024-25	Interface description	Setting
1025-26	Interface description	Setting
1026-27	Interface description	Setting
1027-28	Interface description	Setting
1028-29	Interface description	Setting
1029-30	Interface description	Setting
1030-31	Interface description	Setting
1031-32	Interface description	Setting
1032-33	Interface description	Setting
1033-34	Interface description	Setting
1034-35	Interface description	Setting
1035-36	Interface description	Setting
1036-37	Interface description	Setting
1037-38	Interface description	Setting
1038-39	Interface description	Setting
1039-40	Interface description	Setting
1040-41	Interface description	Setting
1041-42	Interface description	Setting
1042-43	Interface description	Setting
1043-44	Interface description	Setting
1044-45	Interface description	Setting
1045-46	Interface description	Setting
1046-47	Interface description	Setting
1047-48	Interface description	Setting
1048-49	Interface description	Setting
1049-50	Interface description	Setting
1050-51	Interface description	Setting
1051-52	Interface description	Setting
1052-53	Interface description	Setting
1053-54	Interface description	Setting
1054-55	Interface description	Setting
1055-56	Interface description	Setting
1056-57	Interface description	Setting
1057-58	Interface description	Setting
1058-59	Interface description	Setting
1059-60	Interface description	Setting
1060-61	Interface description	Setting
1061-62	Interface description	Setting
1062-63	Interface description	Setting
1063-64	Interface description	Setting
1064-65	Interface description	Setting
1065-66	Interface description	Setting
1066-67	Interface description	Setting
1067-68	Interface description	Setting
1068-69	Interface description	Setting
1069-70	Interface description	Setting
1070-71	Interface description	Setting
1071-72	Interface description	Setting
1072-73	Interface description	Setting
1073-74	Interface description	Setting
1074-75	Interface description	Setting
1075-76	Interface description	Setting
1076-77	Interface description	Setting
1077-78	Interface description	Setting
1078-79	Interface description	Setting
1079-80	Interface description	Setting
1080-81	Interface description	Setting
1081-82	Interface description	Setting
1082-83	Interface description	Setting
1083-84	Interface description	Setting
1084-85	Interface description	Setting
1085-86	Interface description	Setting
1086-87	Interface description	Setting
1087-88	Interface description	Setting
1088-89	Interface description	Setting
1089-90	Interface description	Setting
1090-91	Interface description	Setting
1091-92	Interface description	Setting
1092-93	Interface description	Setting
1093-94	Interface description	Setting
1094-95	Interface description	Setting
1095-96	Interface description	Setting
1096-97	Interface description	Setting
1097-98	Interface description	Setting
1098-99	Interface description	Setting
1099-100	Interface description	Setting

Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No license disc

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025


Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

Front Fender Right



Rear Fender Right



Steering Wheel Trim



Headlight Left



Grill



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

Roof



Windscreen Wiper



Engine



Radiator Cradle



Radiator



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891



CONDITION REPORT

Report No: 2016878508

DATE
15/05/2025

Tyre Front Right



Inner Boot Floor Pan and Spare Wheel Well



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADB514MN6602891