



CONDITION REPORT

Report No: 2016847401

DATE
17/04/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	17/04/2025		M57 Pretoria Road - 1619
Inspection Date	17/04/2025		Kempton Park - GT

Vehicle Data


Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	KIA	Registration Number	CH08PVGP
Model	RIO 1.4 5-DR [2011-2015]	Register Number	
VIN	KNADN512LD6815841	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2024
Color	GREY	Power / Displacement	
Year Model	2013	Paint Finish	M - METALLIC
Km Reading	168,061 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Hooter Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841



CONDITION REPORT

Report No: 2016847401

 DATE
17/04/2025

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.9	2.9	-	
Rear	1.8	1.6	-	
Emergency / Parking	1	0.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/45R17	88W	Royal black	Royal perfor	V	4722	3 mm
Front Right	205/45R17	88W	Royal black	Royal perfor	V	4822	3 mm
Rear Left	205/45R17	88W	Royal black	Royal perfor	V	3418	3 mm
Rear Right	205/45R17	88W	Good ride	Sport sa-37	V	4519	4 mm
Spare	205/45R17	88W	Good ride	Sport sa37	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Vehicle got minor scratches, stone chips and dents.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: KNADN512LD6815841

[illegible]

Shock and brake report

1. **QUESTION**
 2. **ANSWER**
 3. **EXPLANATION**
 4. **REFERENCE**
 5. **REMARKS**
 6. **DATE**
 7. **TIME**
 8. **LOCATION**
 9. **REMARKS**
 10. **REMARKS**
 11. **REMARKS**
 12. **REMARKS**
 13. **REMARKS**
 14. **REMARKS**
 15. **REMARKS**
 16. **REMARKS**
 17. **REMARKS**
 18. **REMARKS**
 19. **REMARKS**
 20. **REMARKS**
 21. **REMARKS**
 22. **REMARKS**
 23. **REMARKS**
 24. **REMARKS**
 25. **REMARKS**
 26. **REMARKS**
 27. **REMARKS**
 28. **REMARKS**
 29. **REMARKS**
 30. **REMARKS**
 31. **REMARKS**
 32. **REMARKS**
 33. **REMARKS**
 34. **REMARKS**
 35. **REMARKS**
 36. **REMARKS**
 37. **REMARKS**
 38. **REMARKS**
 39. **REMARKS**
 40. **REMARKS**
 41. **REMARKS**
 42. **REMARKS**
 43. **REMARKS**
 44. **REMARKS**
 45. **REMARKS**
 46. **REMARKS**
 47. **REMARKS**
 48. **REMARKS**
 49. **REMARKS**
 50. **REMARKS**
 51. **REMARKS**
 52. **REMARKS**
 53. **REMARKS**
 54. **REMARKS**
 55. **REMARKS**
 56. **REMARKS**
 57. **REMARKS**
 58. **REMARKS**
 59. **REMARKS**
 60. **REMARKS**
 61. **REMARKS**
 62. **REMARKS**
 63. **REMARKS**
 64. **REMARKS**
 65. **REMARKS**
 66. **REMARKS**
 67. **REMARKS**
 68. **REMARKS**
 69. **REMARKS**
 70. **REMARKS**
 71. **REMARKS**
 72. **REMARKS**
 73. **REMARKS**
 74. **REMARKS**
 75. **REMARKS**
 76. **REMARKS**
 77. **REMARKS**
 78. **REMARKS**
 79. **REMARKS**
 80. **REMARKS**
 81. **REMARKS**
 82. **REMARKS**
 83. **REMARKS**
 84. **REMARKS**
 85. **REMARKS**
 86. **REMARKS**
 87. **REMARKS**
 88. **REMARKS**
 89. **REMARKS**
 90. **REMARKS**
 91. **REMARKS**
 92. **REMARKS**
 93. **REMARKS**
 94. **REMARKS**
 95. **REMARKS**
 96. **REMARKS**
 97. **REMARKS**
 98. **REMARKS**
 99. **REMARKS**
 100. **REMARKS**

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841



CONDITION REPORT

Report No: 2016847401

DATE
17/04/2025

ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841



CONDITION REPORT

Report No: 2016847401


DATE
17/04/2025



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841



CONDITION REPORT

Report No: 2016847401

DATE
17/04/2025

VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick



ADDITIONAL 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841



CONDITION REPORT

Report No: 2016847401

DATE
17/04/2025


Water level



Hooter



Door Rear Right



Front Fender Right



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841




CONDITION REPORT

Report No: 2016847401

DATE
17/04/2025



Door Front Left



Door Rear Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LD6815841