



CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 16/09/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 16/09/2026        |                     | Kempton Park - GT        |

Vehicle Data

|                 |                                                     |                         |              |
|-----------------|-----------------------------------------------------|-------------------------|--------------|
| Vehicle Type    | LIGHT LOAD VEHICLE                                  | Registered Owner        | MFC          |
| Manufacturer    | GWM                                                 | Registration Number     | LP86NZGP     |
| Model           | P-SERIES 2.0TD CV DLX 6-SP DSL D-CAB PU [2020-2025] | Register Number         |              |
|                 |                                                     | Date Of First Licensing |              |
| VIN             | LGWCCF199PJ626338                                   | Last COR                |              |
| Engine Number   |                                                     | License Expiry Date     | 28/02/2027   |
| Doors           | 4                                                   | Power / Displacement    |              |
| Color           | WHITE                                               | Paint Finish            | TWO COAT UNI |
| Year Model      | 2024                                                | Fuel                    | DIESEL       |
| Km Reading      | 82,589 KM                                           | Transmission            | MANUAL       |
| Cab / Body Type | DOUBLE CAB                                          |                         |              |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



## Damage

## Repair Way

|                                         |         |
|-----------------------------------------|---------|
| Engine Oil Sweat                        | Repair  |
| Hood Lining Dirty                       | Repair  |
| Front Bumper Damaged                    | Repair  |
| Bonnet Dented                           | Repair  |
| Front Fender Left Paintwork • Scratched | Repair  |
| Rear Fender Left Paintwork • Scratched  | Repair  |
| Rear Fender Right Dented                | Repair  |
| Front Fender Right / Inner Tray Damaged | Repair  |
| Door Front Right Dented                 | Repair  |
| Tailgate Dented                         | Repair  |
| Roof Dented                             | Repair  |
| Load Body Dented                        | Repair  |
| Windscreen Chipped                      | Repair  |
| Brake disc 1. Axle left Defective       | Repair  |
| Rim Front Right Scratched               | Repair  |
| Engine mountings Defective              | Replace |
| Front right shock absorber weak         | Replace |

## Brakes

## Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 4.27               | 4.99               | -                |                                  |
| Rear                | 3.08               | 3.64               | -                |                                  |
| Emergency / Parking | 2.24               | 3.51               | -                |                                  |

## Tyres and Rims

## Tyre Specification &amp; Measurement

|             | Size       | Load/Speed Index | Manufacture | Model     | Type* | Production Date | Tread Depth (mm) |
|-------------|------------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left  | 265/65 R17 | 112S             | Dunlop      | Grandtrek | V     | 1225            | 3 mm             |
| Front Right | 265/65 R17 | 112S             | Dunlop      | Grandtrek | V     | 1225            | 3 mm             |
| Rear Left   | 265/65 R17 | 112S             | Dunlop      | Grandtrek | V     | 1225            | 3 mm             |
| Rear Right  | 265/65 R17 | 112S             | Dunlop      | Grandtrek | V     | 1225            | 3 mm             |
| Spare       | 245/70 R17 | 110T             | Choayang    | SU318a    | V     | 0000            | 4 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System                            | Code    | Description               | Status |
|----|-----------------------------------|---------|---------------------------|--------|
| 1  | ESP(ELECTRONIC STABILITY PROGRAM) | U016487 | A/C-FCP NODE MESSAGE LOST |        |

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched. Gear lever worn.

Body • Exterior: Minor dents and scratches on body panels.

Undercarriage: Bottom of engine covered. Vehicle undercarriage dirty

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:

2017299335

DATE

16/09/2026

| DIAGNOSTIC       |          |               |      |
|------------------|----------|---------------|------|
| MAHA             |          |               |      |
| Vehicle:         | Lot:     | Client:       | MAHA |
| Model:           | Year:    | Registration: | 2017 |
| Engine:          | Chassis: | Vehicle:      | MAHA |
| Transmission:    | Color:   | Vehicle:      | MAHA |
| Wheels:          | Color:   | Vehicle:      | MAHA |
| Brakes:          | Color:   | Vehicle:      | MAHA |
| Shock absorbers: | Color:   | Vehicle:      | MAHA |
| Steering:        | Color:   | Vehicle:      | MAHA |
| Lighting:        | Color:   | Vehicle:      | MAHA |
| Exhaust:         | Color:   | Vehicle:      | MAHA |
| Wipers:          | Color:   | Vehicle:      | MAHA |
| Windows:         | Color:   | Vehicle:      | MAHA |
| Doors:           | Color:   | Vehicle:      | MAHA |
| Seats:           | Color:   | Vehicle:      | MAHA |
| Interior:        | Color:   | Vehicle:      | MAHA |
| Exterior:        | Color:   | Vehicle:      | MAHA |
| Engine:          | Color:   | Vehicle:      | MAHA |
| Transmission:    | Color:   | Vehicle:      | MAHA |
| Wheels:          | Color:   | Vehicle:      | MAHA |
| Brakes:          | Color:   | Vehicle:      | MAHA |
| Shock absorbers: | Color:   | Vehicle:      | MAHA |
| Steering:        | Color:   | Vehicle:      | MAHA |
| Lighting:        | Color:   | Vehicle:      | MAHA |
| Exhaust:         | Color:   | Vehicle:      | MAHA |
| Wipers:          | Color:   | Vehicle:      | MAHA |
| Windows:         | Color:   | Vehicle:      | MAHA |
| Doors:           | Color:   | Vehicle:      | MAHA |
| Seats:           | Color:   | Vehicle:      | MAHA |
| Interior:        | Color:   | Vehicle:      | MAHA |
| Exterior:        | Color:   | Vehicle:      | MAHA |

Brake and shock absorber report

| DIAGNOSTIC       |          |               |      |
|------------------|----------|---------------|------|
| MAHA             |          |               |      |
| Vehicle:         | Lot:     | Client:       | MAHA |
| Model:           | Year:    | Registration: | 2017 |
| Engine:          | Chassis: | Vehicle:      | MAHA |
| Transmission:    | Color:   | Vehicle:      | MAHA |
| Wheels:          | Color:   | Vehicle:      | MAHA |
| Brakes:          | Color:   | Vehicle:      | MAHA |
| Shock absorbers: | Color:   | Vehicle:      | MAHA |
| Steering:        | Color:   | Vehicle:      | MAHA |
| Lighting:        | Color:   | Vehicle:      | MAHA |
| Exhaust:         | Color:   | Vehicle:      | MAHA |
| Wipers:          | Color:   | Vehicle:      | MAHA |
| Windows:         | Color:   | Vehicle:      | MAHA |
| Doors:           | Color:   | Vehicle:      | MAHA |
| Seats:           | Color:   | Vehicle:      | MAHA |
| Interior:        | Color:   | Vehicle:      | MAHA |
| Exterior:        | Color:   | Vehicle:      | MAHA |
| Engine:          | Color:   | Vehicle:      | MAHA |
| Transmission:    | Color:   | Vehicle:      | MAHA |
| Wheels:          | Color:   | Vehicle:      | MAHA |
| Brakes:          | Color:   | Vehicle:      | MAHA |
| Shock absorbers: | Color:   | Vehicle:      | MAHA |
| Steering:        | Color:   | Vehicle:      | MAHA |
| Lighting:        | Color:   | Vehicle:      | MAHA |
| Exhaust:         | Color:   | Vehicle:      | MAHA |
| Wipers:          | Color:   | Vehicle:      | MAHA |
| Windows:         | Color:   | Vehicle:      | MAHA |
| Doors:           | Color:   | Vehicle:      | MAHA |
| Seats:           | Color:   | Vehicle:      | MAHA |
| Interior:        | Color:   | Vehicle:      | MAHA |
| Exterior:        | Color:   | Vehicle:      | MAHA |

Diagnostic report page 1

| DIAGNOSTIC       |          |               |      |
|------------------|----------|---------------|------|
| MAHA             |          |               |      |
| Vehicle:         | Lot:     | Client:       | MAHA |
| Model:           | Year:    | Registration: | 2017 |
| Engine:          | Chassis: | Vehicle:      | MAHA |
| Transmission:    | Color:   | Vehicle:      | MAHA |
| Wheels:          | Color:   | Vehicle:      | MAHA |
| Brakes:          | Color:   | Vehicle:      | MAHA |
| Shock absorbers: | Color:   | Vehicle:      | MAHA |
| Steering:        | Color:   | Vehicle:      | MAHA |
| Lighting:        | Color:   | Vehicle:      | MAHA |
| Exhaust:         | Color:   | Vehicle:      | MAHA |
| Wipers:          | Color:   | Vehicle:      | MAHA |
| Windows:         | Color:   | Vehicle:      | MAHA |
| Doors:           | Color:   | Vehicle:      | MAHA |
| Seats:           | Color:   | Vehicle:      | MAHA |
| Interior:        | Color:   | Vehicle:      | MAHA |
| Exterior:        | Color:   | Vehicle:      | MAHA |
| Engine:          | Color:   | Vehicle:      | MAHA |
| Transmission:    | Color:   | Vehicle:      | MAHA |
| Wheels:          | Color:   | Vehicle:      | MAHA |
| Brakes:          | Color:   | Vehicle:      | MAHA |
| Shock absorbers: | Color:   | Vehicle:      | MAHA |
| Steering:        | Color:   | Vehicle:      | MAHA |
| Lighting:        | Color:   | Vehicle:      | MAHA |
| Exhaust:         | Color:   | Vehicle:      | MAHA |
| Wipers:          | Color:   | Vehicle:      | MAHA |
| Windows:         | Color:   | Vehicle:      | MAHA |
| Doors:           | Color:   | Vehicle:      | MAHA |
| Seats:           | Color:   | Vehicle:      | MAHA |
| Interior:        | Color:   | Vehicle:      | MAHA |
| Exterior:        | Color:   | Vehicle:      | MAHA |

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:

2017299335

DATE

16/09/2026



LICENSE DISC



VIN PLATE OR STICKER




ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



Spare Wheel Accessories



Jack



Hood Lining



Rear Fender Right



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



Front Fender Left



Front Fender Left



Windscreen



Rear Fender Left



Rear Fender Left



Tailgate

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



Load Body



Water level



Front Fender Right / Inner Tray



Rim Front Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: LGWCCF199PJ626338



## CONDITION REPORT



Report No:  
2017299335  
DATE  
16/09/2026



Brake disc 1. Axle left




Engine mountings



Engine



Water level



Door Front Right



Roof

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: LGWCCF199PJ626338