



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	05/05/2025		M57 Pretoria Road - 1619
Inspection Date	05/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HAVAL	Registration Number	JM52NYGP
Model	H2 1.5 CITY [2020-2022]	Register Number	
VIN	LGWEE4A44LH913261	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	BLUE	Power / Displacement	
Year Model	2020	Paint Finish	TWO COAT UNI
Km Reading	157,129 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Fog Light Front Right Damaged	Replace
Headlight Left Damaged	Replace
Seat Front Right Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Cracked	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

Damage	Repair Way
Rim Front Left Scratched	Repair
Belly plates Damaged	Repair
Body and Exterior	Vehicle license disk missing
Interior	Vehicle interior dirty and some panels scratched
Engine	Engine bay dirty.
Body and Exterior	Dents and scratches on some body panels
Engine	Foreign substance on radiator and expansion bottle
Vehicle electronics malfunctioning	Repair
Tyres and rims	Front and rear tyre sizes different

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.57	3.12	-	
Rear	2.23	2.17	-	
Emergency / Parking	0.86	0.84	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55 R18	98V	Apollo	Apterra	V	1222	1 mm
Front Right	225/55 R18	98V	Apollo	Apterra	V	1222	2 mm
Rear Left	235/55 R18	100H	Kumho	Solus	V	4219	1 mm
Rear Right	235/55 R18	100H	Kumho	Solus	V	4219	1 mm
Spare	T115/85 R18	115M	Choayang	Temporary	V	4419	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM(ENGINE CONTROL MODULE)	U110116	CAN MODULE COMMUNICATION VOLTAGE LOW	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: LGWEE4A44LH913261

**CONDITION REPORT****Report No: 2016865486****DATE**
05/05/2025

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

BRAKE AND SHOCK ABSORBER REPORT			
Client Name	Client Address	Client Phone	Client Email
Vehicle Make	Vehicle Model	Vehicle Year	Vehicle Colour
Vehicle VIN	Vehicle Mileage	Vehicle Engine	Vehicle Transmission
Vehicle Tyre Size	Vehicle Tyre Brand	Vehicle Tyre Condition	Vehicle Tyre Pressure
Vehicle Brake Pad Thickness	Vehicle Brake Disc Condition	Vehicle Shock Absorber Condition	Vehicle Suspension Condition
Vehicle Steering Condition	Vehicle Alignment	Vehicle Wheel Balance	Vehicle Wheel Condition
Vehicle Chassis Condition	Vehicle Body Condition	Vehicle Paint Condition	Vehicle Glass Condition
Vehicle Interior Condition	Vehicle Exterior Condition	Vehicle Safety Condition	Vehicle Emissions Condition
Vehicle Overall Condition	Vehicle Inspection Status	Vehicle Inspection Date	Vehicle Inspection Location

Brake and shock absorber report

DIAGNOSTIC REPORT PAGE 1			
Client Name	Client Address	Client Phone	Client Email
Vehicle Make	Vehicle Model	Vehicle Year	Vehicle Colour
Vehicle VIN	Vehicle Mileage	Vehicle Engine	Vehicle Transmission
Vehicle Tyre Size	Vehicle Tyre Brand	Vehicle Tyre Condition	Vehicle Tyre Pressure
Vehicle Brake Pad Thickness	Vehicle Brake Disc Condition	Vehicle Shock Absorber Condition	Vehicle Suspension Condition
Vehicle Steering Condition	Vehicle Alignment	Vehicle Wheel Balance	Vehicle Wheel Condition
Vehicle Chassis Condition	Vehicle Body Condition	Vehicle Paint Condition	Vehicle Glass Condition
Vehicle Interior Condition	Vehicle Exterior Condition	Vehicle Safety Condition	Vehicle Emissions Condition
Vehicle Overall Condition	Vehicle Inspection Status	Vehicle Inspection Date	Vehicle Inspection Location

Diagnostic report page 1

DIAGNOSTIC REPORT PAGE 2			
Client Name	Client Address	Client Phone	Client Email
Vehicle Make	Vehicle Model	Vehicle Year	Vehicle Colour
Vehicle VIN	Vehicle Mileage	Vehicle Engine	Vehicle Transmission
Vehicle Tyre Size	Vehicle Tyre Brand	Vehicle Tyre Condition	Vehicle Tyre Pressure
Vehicle Brake Pad Thickness	Vehicle Brake Disc Condition	Vehicle Shock Absorber Condition	Vehicle Suspension Condition
Vehicle Steering Condition	Vehicle Alignment	Vehicle Wheel Balance	Vehicle Wheel Condition
Vehicle Chassis Condition	Vehicle Body Condition	Vehicle Paint Condition	Vehicle Glass Condition
Vehicle Interior Condition	Vehicle Exterior Condition	Vehicle Safety Condition	Vehicle Emissions Condition
Vehicle Overall Condition	Vehicle Inspection Status	Vehicle Inspection Date	Vehicle Inspection Location

Diagnostic report page 2

DIAGNOSTIC REPORT PAGE 3			
Client Name	Client Address	Client Phone	Client Email
Vehicle Make	Vehicle Model	Vehicle Year	Vehicle Colour
Vehicle VIN	Vehicle Mileage	Vehicle Engine	Vehicle Transmission
Vehicle Tyre Size	Vehicle Tyre Brand	Vehicle Tyre Condition	Vehicle Tyre Pressure
Vehicle Brake Pad Thickness	Vehicle Brake Disc Condition	Vehicle Shock Absorber Condition	Vehicle Suspension Condition
Vehicle Steering Condition	Vehicle Alignment	Vehicle Wheel Balance	Vehicle Wheel Condition
Vehicle Chassis Condition	Vehicle Body Condition	Vehicle Paint Condition	Vehicle Glass Condition
Vehicle Interior Condition	Vehicle Exterior Condition	Vehicle Safety Condition	Vehicle Emissions Condition
Vehicle Overall Condition	Vehicle Inspection Status	Vehicle Inspection Date	Vehicle Inspection Location

Diagnostic report page 3

DIAGNOSTIC REPORT PAGE 4			
Client Name	Client Address	Client Phone	Client Email
Vehicle Make	Vehicle Model	Vehicle Year	Vehicle Colour
Vehicle VIN	Vehicle Mileage	Vehicle Engine	Vehicle Transmission
Vehicle Tyre Size	Vehicle Tyre Brand	Vehicle Tyre Condition	Vehicle Tyre Pressure
Vehicle Brake Pad Thickness	Vehicle Brake Disc Condition	Vehicle Shock Absorber Condition	Vehicle Suspension Condition
Vehicle Steering Condition	Vehicle Alignment	Vehicle Wheel Balance	Vehicle Wheel Condition
Vehicle Chassis Condition	Vehicle Body Condition	Vehicle Paint Condition	Vehicle Glass Condition
Vehicle Interior Condition	Vehicle Exterior Condition	Vehicle Safety Condition	Vehicle Emissions Condition
Vehicle Overall Condition	Vehicle Inspection Status	Vehicle Inspection Date	Vehicle Inspection Location

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

RF TYRE TREAD



Spare wheel and Accessories



No license disc



VIN PLATE OR STICKER



ENGINE 1



Front chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261




CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025


Rear chassis



Oil cap and dipstick



Seat Front Right



Door Sealing Rubber Front Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

Door Front Right



Front Fender Right



Side Mirror Right



Front Bumper



Front Bumper



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

Headlight Left



Front Fender Left



Windscreen



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025


Rear bumper



Rear bumper



Boot Lid / Hatch door



Parking Brake Performance



Rim Front Left



Fog Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261



CONDITION REPORT

Report No: 2016865486

DATE
05/05/2025

Belly plates



Water level



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A44LH913261