

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	12/01/2024		M57 Pretoria Road - 1619
Inspection Date	12/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	GWM	Registration Number	FB19RHGP
Model	C50T	Register Number	
VIN	LGWEF3K59EF620811	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/03/2023
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	225,894 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Hoses Oil Leak	Repair
Center Console / Cubbyhole + Lid Defective	Repair
Air Conditioner Insufficient	Replace
Tail Light Left Damaged	Replace
Tail Light Right Scratched	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Defective	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Belt Front Right Defective	Replace
Hood Lining Dirty	Repair
Door Handle Front Left Damaged	Replace
Door Handle Front Right Defective	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Gear Lever Dust Boot Defective	Repair
Steering Wheel Trim Damaged	Repair
Number Plate Front Dented	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Bonnet slam plate (Shock tower/ Inner tray) Welded	Replace
B • Pillar Left Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair

Damage	Repair Way
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Rocker Panel Left Dented	Repair
Rocker Panel Right Damaged	Repair
Roof Dented	Repair
Windscreen Chipped	Replace
Wheel bearing Front Right Loose / Excessive Play	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Control Arm Bush(es) Rear Axle Left Cracked	Replace
Control Arm Bush(es) Rear Axle Right Cracked	Replace
Tyre Rear Right Damaged	Replace
Chassis Scratched	Repair
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
Engine Noise Excessive	Repair
Engine Performance Idling / Hunting	Repair
Warning lights illuminated on dashboard.	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.12	3.28	-	
Rear	1.69	1.9	-	
Emergency / Parking	1.75	1.73	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55 R16	91V	Zextour	Comfort	V	1522	2 mm
Front Right	205/55 R16	91V	Zextour	Comfort	V	1522	2 mm
Rear Left	205/55 R16	91V	Zextour	Comfort	V	1522	4 mm
Rear Right	205/55 R16	91V	Zextour	Comfort	V	1522	4 mm
Spare	205/55 R16	91V	Hankook	Kinergy	V	4419	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM(ENGINE SYSTEM)	P0571	BRAKE SWITCH'A' CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Engine bay dirty.Brake fluid level ok.Battery loose.
Electrical Components and

Concluding Remarks

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

Car				Car			
Name of client				Car			
Address, etc.				Registration			
Telephone				Make			
Test date				Model			
Test time				VIN			
Test results				Results			
Chassis test				Pass			
Steering test				Pass			
Shock absorber test				Pass			
Brake test				Pass			

Brake and shock absorber report

Car				Car			
Name of client				Car			
Address, etc.				Registration			
Telephone				Make			
Test date				Model			
Test time				VIN			
Test results				Results			
Chassis test				Pass			
Steering test				Pass			
Shock absorber test				Pass			
Brake test				Pass			

Diagnostic report page 1

Car				Car			
Name of client				Car			
Address, etc.				Registration			
Telephone				Make			
Test date				Model			
Test time				VIN			
Test results				Results			
Chassis test				Pass			
Steering test				Pass			
Shock absorber test				Pass			
Brake test				Pass			

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

VIN: LGWEF3K59EF620811

7 / 18



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC

VIN: LGWEF3K59EF620811


8 / 18



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Manual Transmission

VIN: LGWEF3K59EF620811

10 / 18



Front Bumper



Front Bumper



Bonnet



Headlight Left



Headlight Right



Windscreen

VIN: LGWEF3K59EF620811

12 / 18



Front Fender Left



Front Fender Right



Door Front Right



Side Mirror Right




Door Rear Right



Rear Fender Right

VIN: LGWEF3K59EF620811


14 / 18



Seat Front Right



Steering Wheel Trim

620811
15 / 18

Hood Lining



Center Console / Cubbyhole + Lid



Rear bumper



Rear bumper

VIN: LGWEF3K59EF620811

16 / 18



Boot Lid / Hatch door



VIN: LGWEF3K59FF620811

17 / 18

Rear Fender Left



Door Rear Left



Door Front Left



Roof



Seat Rear

VIN: LGWEF3K59EF620811

18 / 18



Sill Panel Right



Sill Panel Right



Sill Panel Left



Door Sealing Rubber Rear Left



Seat Rear



Seat Front Left



B • Pillar Left



Sill Panel Left



Door Handle Front Left



Seat Belt Front Right



Gear Lever Dust Boot



Air Conditioner



Number Plate Front



Water level



Tail Light Left



Tail Light Right



Wheel bearing Front Right



Rocker Panel Right



Rocker Panel Left



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right



Belly plates



Gearbox



Engine



Engine



Chassis




Control Arm Bush(es) Rear Axle Left



Control Arm Bush(es) Rear Axle Right



Belly plates



Tyre Rear Right



Water level



Hoses



Bonnet slam plate (Shock tower/ Inner tray)



Door Handle Front Right



CONDITION REPORT

Report No: 2016226947

DATE
12/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za