



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/09/2026		M57 Pretoria Road - 1619
Inspection Date	11/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HAVAL	Registration Number	MW99VGGP
Model	H6 2.0T GT SUPER LUXURY AWD DCT [2022-2025]	Register Number	
		Date Of First Licensing	
VIN	LGWFF6A50PH947080	Last COR	
Engine Number		License Expiry Date	28/02/2027
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT UNI
Year Model	2023	Fuel	PETROL
Km Reading	39,852 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:

2017297345

DATE


11/09/2026

Damage

Repair Way

Indicator Light Front Right Scratched
 Seat Rear Dirty
 Carpet Front Damaged
 Boot Carpet Damaged
 Bonnet Dented
 C • Pillar Left Paintwork • Scratched
 Door Front Left Paintwork • Scratched
 Rear bumper Paintwork • Scratched
 Windscreen Cracked
 Sub Frame Scratched
 Belly plates Damaged
 Gearbox Mountings Damaged
 Boot spoiler scratched

Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Repair
 Replace
 Repair
 Repair
 Repair
 Repair



Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/55Z R19	105W	Royalblack	Explorer	V	4325	3 mm
Front Right	235/55Z R19	105W	Royalblack	Explorer	V	4325	3 mm
Rear Left	235/55Z R19	105W	Royalblack	Explorer	V	4325	4 mm
Rear Right	235/55Z R19	105W	Royalblack	Explorer	V	4325	4 mm
Spare	T135/90 R17	104M	Linglong	Temporary	V	2523	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	SRS(SUPPLEMENTAL RESTRAINT SYSTEM)	U110116	DIAGNOSTIC VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches on body panels.
Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:

2017297345

DATE

11/09/2026

REPORT INFORMATION			
Report No:	2017297345	Client:	Mr. J. J. J. J.
Report Date:	2026/09/14	Vehicle:	2021 Toyota Hilux
Report Time:	11:44 AM	Location:	12345678901234567890
Test Results			
Test Name	Result	Unit	Remarks
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber

Shock absorber report

VEHICLE DIAGNOSTIC REPORT			
Report No:	2017297345	Client:	Mr. J. J. J. J.
Report Date:	2026/09/14	Vehicle:	2021 Toyota Hilux
Report Time:	11:44 AM	Location:	12345678901234567890
Test Results			
Test Name	Result	Unit	Remarks
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber

Diagnostic report page 1

VEHICLE DIAGNOSTIC REPORT			
Report No:	2017297345	Client:	Mr. J. J. J. J.
Report Date:	2026/09/14	Vehicle:	2021 Toyota Hilux
Report Time:	11:44 AM	Location:	12345678901234567890
Test Results			
Test Name	Result	Unit	Remarks
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber

Diagnostic report page 2

VEHICLE DIAGNOSTIC REPORT			
Report No:	2017297345	Client:	Mr. J. J. J. J.
Report Date:	2026/09/14	Vehicle:	2021 Toyota Hilux
Report Time:	11:44 AM	Location:	12345678901234567890
Test Results			
Test Name	Result	Unit	Remarks
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber

Diagnostic report page 3

VEHICLE DIAGNOSTIC REPORT			
Report No:	2017297345	Client:	Mr. J. J. J. J.
Report Date:	2026/09/14	Vehicle:	2021 Toyota Hilux
Report Time:	11:44 AM	Location:	12345678901234567890
Test Results			
Test Name	Result	Unit	Remarks
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber
Shock absorber	Pass	mm	Shock absorber

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



RF TYRE TREAD



Spare Wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



Rear chassis



Boot spoiler



Oil cap and dipstick



Carpet Front



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



Seat Rear



C • Pillar Left



Door Front Left



Door Front Left



Windscreen



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



Indicator Light Front Right



Water level



Belly plates



Sub Frame



Sub Frame



Gearbox Mountings

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080



CONDITION REPORT



Report No:
2017297345
DATE
11/09/2026



Belly plates



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A50PH947080