



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/09/2026		M57 Pretoria Road - 1619
Inspection Date	29/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	SUZUKI	Registration Number	MK08CGGP
Model	ERTIGA 1.5 GA MPV [2022-2025]	Register Number	
VIN	MA3BNC22S00A30680	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2026
Color	SILVER	Power / Displacement	
Year Model	2025	Paint Finish	TWO COAT UNI
Km Reading	39,088 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:

2017304546

DATE

29/09/2026

Damage

Repair Way

Radio/CD/USB Defective	Repair
Headlight Right Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
A • Pillar Right Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Rear Fender Right Dented	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Dented	Repair
Sill Panel Right Damaged	Repair
Rim Rear Left Dented	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Belly plates Damaged	Replace
Triangle Missing	Replace
Front left shock absorber weak	Replace
Deceleration service brake defective	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.12	2.07	-	
Rear	1.68	1.88	-	
Emergency / Parking	1.4	1.47	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Bridgestone	Ecopia	V	1325	2 mm
Front Right	185/65 R15	88H	Bridgestone	Ecopia	V	1325	4 mm
Rear Left	185/65 R15	88H	Bridgestone	Ecopia	V	1325	5 mm
Rear Right	185/65 R15	88H	Bridgestone	Ecopia	V	1325	5 mm
Spare	185/65 R15	88H	Bridgestone	Ecopia	V	1325	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP(ANTI-LOCK BRAKING SYSTEM/ELECTRONIC STABIL	U0126	LOST COMMUNICATION WITH STEERING ANGLE SENSOR MODU	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to front of vehicle.
Axle and Suspension: Front suspension faulty.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report page 1

/ Bulletin/Title		Date / Time	Page	Report ID
U0121	Lost communication with ABS or electronic stability program control module	2017-04-24 10:00:25	1	SAW0270102904802
B1640	Vehicle speed data invalid			History
CGW(Central gateway control module) (1 DTC)				
DTC	(Description)			Status
U0121-62	Lost communication with ABS or electronic stability program control module			History

Technician Notes
2017.3.45-66

Customer name: _____

Technician: _____

Date: _____

9000 (Please do not copy the report to any cloud.)

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:

2017304546

DATE

29/09/2026



Spare Wheel Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026



Oil cap and dipstick



Front Fender Left



Door Rear Left



Rear Fender Right



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:

2017304546

DATE

29/09/2026



A • Pillar Right



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Rear Wheel Right



Rim Rear Left



Radio/CD/USB



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:

2017304546

DATE

29/09/2026



Headlight Right



Sill Panel Right



Front Bumper



Front Bumper



Front Bumper



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680



CONDITION REPORT



Report No:
2017304546
DATE
29/09/2026



Water level



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3BNC22S00A30680