



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/05/2024		M57 Pretoria Road - 1619
Inspection Date	28/05/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HONDA	Registration Number	JK67XNGP
Model	MAZE	Register Number	
VIN	MAKDF5630K4000339	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/01/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	191,533 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Wiring Defective	Repair
Battery clamps Defective	Repair
Air conditioner pipes Defective	Repair
Bonnet hinges Damaged	Replace
Windscreen Wiper Worn	Replace
Tail Light Left Cracked	Replace
Headlight Right Chipped	Replace
Seat Front Right Torn / Cut	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Side Mirror Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Residual Traces of Repair	Repair
Bonnet slam plate (Shock tower/ Inner tray) Residual Traces of Repair	Repair
C • Pillar Left Welded	Replace
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Replace
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Damaged	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5630K4000339

1 / 21



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Damage	Repair Way
Sill Panel Left Residual Traces of Repair	Repair
Roof Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Rear Axle Damaged	Replace
Tyre Front Right Excessive Wear & Tear	Replace
Tyre Rear Left Excessive Wear & Tear	Replace
Tyre Rear Right Excessive Wear & Tear	Replace
Spare Tyre Excessive Wear & Tear	Replace
Main Beam Left Welded	Replace
Catalytic converter Welded	Replace
Radiator Cradle Welded	Replace
Body exterior	Sparewheel damage
Body exterior	Signs of spray work done on all body panels
Electronics malfunction	Both front electric mirrors malfunction.
Residual traces of welding on chassis leg extensio	radiator cradle signs of welding.
Axle and suspension	Both front control arm bushes covered
Signs of welding on some body panels	Repair

Brakes**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	2.2	2.8	-	
Rear	1.6	1.6	-	
Emergency / Parking	1.4	1.3	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/70R14	84T	MRF	ZVT	V	2919	1 mm
Front Right	185/65R15	88H	Nexen	Nblue	V	3618	3 mm
Rear Left	175/65R15	84H	Firestone	Touring	V	3516	1 mm
Rear Right	185/60R15	84H	Rapid	P309	V	3019	1 mm
Spare	185/65R15	92T	Barum	Brillantis	V	//////	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Residual traces of poor repair work done.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksdorp, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

**CONDITION REPORT**

VIN: MAKDF5620K4000330

Report No: 201839939

2 / 21

DATE

28/05/2024

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016395930

VIN: MAKDF5630K4000339

DATE
28/05/2024

Shock and brake report



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



CONDITION REPORT

Report No: 2016395930

DATE

VIN: MAKDF5630K4000339

28/05/2024

4 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE

28/05/2024

VIN: MAKDF5630K4000339

5 / 21



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

6 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395939

DATE
28/05/2024

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



Sparewheel well



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

8 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Sparewheel well



Sparewheel well



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

10 / 21



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

CHASSIS



Rear end



R/F headlight clips broken



L/F headlight cover broken.



Oil cap and dipstick



Coolant reservoir



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

12 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Door Sealing Rubber Rear Right



Door Sealing Rubber Rear Right

VIN: MAKDF5630K4000339
13 / 21

Rear Fender Right



Spare Tyre



Boot Lid / Hatch door



Boot Lid / Hatch door



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

14 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Tail Light Left



Door Sealing Rubber Rear Left



Side Mirror Left



Side Mirror Left



Windscreen



Windscreen Wiper



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

16 / 21

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Bonnet



Roof

VIN: MAKDF5630K4000339

17 / 21



Front Fender Left



Side Mirror Right



Bonnet



Bonnet



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

18 / 21



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Bonnet hinges



Bonnet hinges

VIN: MAKDF5630K4000339

19 / 21



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Front Bumper



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

VIN: MAKDF5630K4000339

20 / 21



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Air conditioner pipes



Radiator Cradle



Radiator Cradle



Radiator Cradle



Radiator Cradle





CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Engine Wiring



Battery clamps



Front Fender Right



Water level



Headlight Right



Door Front Right



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Door Rear Right



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Grill



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Front Bumper



Front Bumper



Door Front Left



Door Rear Left



Rear Fender Left



Rear Fender Left / Inner Tray



CONDITION REPORT

Report No: 2016395930


DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Rear bumper



Rear bumper



Rear bumper



Rear bumper



Tyre Front Right



Catalytic converter



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Catalytic converter



Radiator Cradle



Radiator Cradle



Sill Panel Left



Sill Panel Left



Tyre Rear Left



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Main Beam Left



Main Beam Left



Main Beam Left



Rear Fender Left / Inner Tray



Rear Fender Left / Inner Tray



Tyre Rear Right



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016395930

DATE
28/05/2024

Rear Axle



Seat Front Right



C • Pillar Left



C • Pillar Left

**CONDITION REPORT**

Report No: 2016395930

DATE
28/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za