

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	31/03/2025		M57 Pretoria Road - 1619
Inspection Date	31/03/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	CZ41XJGP
Model	I20 1.4 GLIDE 5-DR [2012-2015]	Register Number	
VIN	MALBB51CLDM554451	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2014	Paint Finish	TWO COAT UNI
Km Reading	97,134 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Sun Visor Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Rear bumper Paintwork • Scratched	Repair
Shock Absorber Front Left Leak	Replace
Ball Joint(s) Front Axle Left Defective	Replace
Tyre Rear Right Defective	Replace
Rim Front Left Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Spare Wheel Dented	Repair
Chassis Dented	Repair
Sub Frame Damaged	Repair
Silencer Defective	Repair
Belly plates Damaged	Repair
Fuel Tank Sweat	Repair
Fuel Lines Sweat	Repair

Damage	Repair Way
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Airbag warning light illuminated on dashboard	Repair
Front left shock absorber weak	Replace
Undercarriage	Vehicle undercarriage dirty
Body and Exterior	Minor dents and scratches on some body panels

Brakes

Brake Test Results

	Left	Right	Axe Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.8	2.83	-	
Rear	1.67	1.79	-	
Emergency / Parking	1.22	1.11	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/50 R16	84V	Dunlop	Sp-Sport	V	1523	4 mm
Front Right	195/50 R16	84V	Dunlop	Sp-Sport	V	1523	3 mm
Rear Left	195/50 R16	88V	Apollo	Alnac	V	3620	3 mm
Rear Right	195/50 R16	88V	Apollo	Alnac	V	3620	4 mm
Spare	195/50 R16	84H	Kumho	Solus	V	0413	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1346	DRIVER AIRBAG(DAB) RESISTANCE TOO HIGH(1ST STAGE)	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBB51CLDM554451



CONDITION REPORT

Report No: 2016821942

DATE
31/03/2025

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBB51CLDM554451



CONDITION REPORT

Report No: 2016821942

DATE
31/03/2025

Brake and shock absorber report

Front axle	0	0 km/h	Rear axle	+9	0 km/h	
Shock absorber test (JN133000)						
Front axle	0.01	0.01	Right	0.01	0.01	D ₁
Front axle	0.03	0.04	Left	0.01	0.01	D ₂
Rear axle	0.01	0.04	Right	0.02	0.02	D ₃
Rear axle	0.01	0.04	Left	0.02	0.02	D ₄
Total weight				1.78	1.78	D ₅
Brake test						
	Brake force					
Front axle	300	150	Front-left			D ₆
Front axle	7.00	1.80	2.20	1.00	1.00	D ₇
Parking brake	1.22	0.32	1.11	0.38	0.38	D ₈
Rear axle	1.67	0.40	1.79	0.38	0.38	R ₉
Total evaluation value						D ₁₀
Brake lining service life		82 %				S ₁₁
Deceleration starting value		21 %	Total weight		1.78 kg	P ₁₂

Shock absorber readings

The screenshot shows a diagnostic report titled "Hyundai VEHICLE DIAGNOSTIC REPORT" for a vehicle with VIN KMHBL1ABXH3000001. The report includes sections for "Vehicle Information", "Diagnostic Log", "Fault Codes", "SRS Status", "ECM Status", "PCM Status", "TCCU Status", "DTC Status", "FIR Status", and "FIR Log". A red box highlights the "PCM Status" section, which displays various status indicators such as "PCM Status: OK", "PCM Power: OK", "PCM Ground: OK", "PCM Short: OK", "PCM Open: OK", "PCM VSS: OK", "PCM VDO: OK", "PCM VTEC: OK", "PCM VVT: OK", "PCM VTEC: OK", "PCM VVT: OK", and "PCM VTEC: OK".

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBB51CLDM554451



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Sun Visor Right



Front Bumper



Front Bumper



Door Front Right



Door Rear Right



Door Rear Left



Rear Fender Left



Door Front Left



Rear bumper



Rear bumper



Rim Spare Wheel



Rim Rear Left




Rim Front Left



Shock Absorber Front Left



Belly plates



Sub Frame



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Ball Joint(s) Front Axle Left



Chassis



Fuel Tank



Tyre Rear Right



Silencer



Fuel Lines



Water level



Water level



Sun Visor Right



Front Bumper



Front Bumper



Door Front Right



Door Rear Right



Door Rear Left



Rear Fender Left



Door Front Left



Rear bumper



Rear bumper



Rim Spare Wheel



Rim Rear Left




Rim Front Left



Shock Absorber Front Left



Belly plates



Sub Frame



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Ball Joint(s) Front Axle Left



Chassis



Fuel Tank



Tyre Rear Right



Silencer



Fuel Lines



Water level



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBB51CLDM554451