



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	BC99KHGP
Model	I20 1.6 GLS 5-DR [2009-2013]	Register Number	
VIN	MALBC51DLBM257722	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2024
Color	GREY	Power / Displacement	
Year Model	2011	Paint Finish	TWO COAT METALLIC
Km Reading	184,326 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:


2017305240

DATE

30/09/2026

Damage

Repair Way



Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Seat Front Right Damaged	Repair
Seat Rear Worn	Repair
Sun Visor Left Damaged	Replace
Sun Visor Right Damaged	Replace
Door Handle Front Left Damaged	Replace
Door Handle Front Right Damaged	Replace
Door Handle Rear Left Damaged	Repair
Side Mirror Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Replace
Windscreen Damaged	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Bolt(s) / Nut(s) Front Wheel Right Damaged	Replace
Rear tyres size differs	Replace
Battery loose	Repair
Left front door does not open	Repair
Driver side door does not open from outside	Repair
Driver's door electric window does not work.	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.52	2.75	-	
Rear	2.08	1.77	-	
Emergency / Parking	1.35	0.76	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R15	84H	Kumho	Radial	V	2521	0 mm
Front Right	185/60R15	88H	Dunlop	Radial	V	1820	0 mm
Rear Left	185/65R15	92T	Barum	Radial	V	0121	0 mm
Rear Right	185/60R15	84H	Onyx	Radial	V	3219	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS. REPAIR WORK DONE TO VEHICLE BELOW STANDARD / FOREIGN SUBSTANCE ON OIL FILLER CAP.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



INTERIOR (FRONT DRIVER DOOR)



Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:

2017305240

DATE _____

30/09/2026



LR TYRE TREAD



RR TYRE TREAD

[illegible]

Brake test.



Diagnostic.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



Rear bumper



Rear bumper




Boot Lid / Hatch door



Door Rear Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



Rear Fender Right



Windscreen



Side Mirror Right



Side Mirror Left



Door Handle Front Right



Door Handle Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



Door Handle Rear Left



Sun Visor Left



Sun Visor Right



Central Air Vent



Bolt(s) / Nut(s) Front Wheel Right



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722



CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



Tyre Rear Right



Tyre Front Right



Engine



Tyre Front Left



Tyre Rear Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722




CONDITION REPORT



Report No:
2017305240
DATE
30/09/2026



Engine Management Lights



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBC51DLBM257722