



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/09/2026		M57 Pretoria Road - 1619
Inspection Date	25/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	JC11XYGP
Model	ETIOS	Register Number	
VIN	MBJB29BTX00122730	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/04/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	263,624 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MBJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Damage	Repair Way
Under bonnet insulation cover Damaged	Repair
Heater control Damaged	Replace
Switch Electrical Window Winder front left Malfunction	Replace
Tail Light Right Damaged	Replace
Fog Light Front Left Defective	Repair
Fog Light Front Right Cracked	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Sun Visor Right Excessive Wear & Tear	Repair
Hood Lining Dirty	Repair
Boot Carpet Damaged	Repair
Gear Lever Dust Boot Damaged	Repair
Clutch Pedal Rubber Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Damaged	Repair
Front Bumper Damaged	Replace
Bonnet Damaged	Repair
C • Pillar Left Dented	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Residual Traces of Repair	Repair
Door Front Right Damaged	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Flaking	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Fuel Flap Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Tie Rod End right Damaged	Replace
Shock Absorber Front Left Leak	Replace
Shock Absorber Mounting Front Left Damaged	Replace
Shock Absorber Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Damaged	Replace
Rim Front Left Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Chassis Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026

Damage	Repair Way
Engine to silencer pipe Damaged	Replace
Radiator Cradle Damaged	Replace
Clutch Operation Insufficient	Repair
Number plate light missing	Replace
Spare wheel missing	Replace
Interior boot lock plastic trim damaged	Replace
Boot release cable missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.4	2.69	-	
Rear	1.83	1.87	-	
Emergency / Parking	0.8	1.37	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R15	84H	Bridgestone	Turanza	V	3218	0 mm
Front Right	185/60 R15	84H	Bridgestone	Turanza	V	3218	0 mm
Rear Left	185/60 R15	84H	Bridgestone	Turanza	V	3218	0 mm
Rear Right	185/60 R15	84H	Dunlop	Sp-Sport	V	4421	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P1604	STARTABILITY FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Signs of impact damage to front and rear of vehicle. Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026

work on body panels. Dents and scratches on body panels.
Axle and Suspension: Excessive noise coming from front suspension.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:

2017302467

DATE

25/09/2026

Car				Car			
Model:	2017 Toyota Aygo	Year:	2017	Model:	2017 Toyota Aygo	Year:	2017
Registration:	2017	Manufacturer:	TOYOTA	Registration:	2017	Manufacturer:	TOYOTA
Test date:	25/09/2026	Test time:	11:54	Test date:	25/09/2026	Test time:	11:54
Test results				Test results			
Side-slip test				Side-slip test			
Front axle	+ 1.00%	Rear axle	+ 2.00%	Front axle	+ 1.00%	Rear axle	+ 2.00%
Shock absorber test				Shock absorber test			
Front axle	Left: 0.00, Right: 0.00	Distance	100.00	Front axle	Left: 0.00, Right: 0.00	Distance	100.00
Rear axle	Left: 0.00, Right: 0.00	Distance	100.00	Rear axle	Left: 0.00, Right: 0.00	Distance	100.00
Brake test				Brake test			
Front axle	Left: 0.00, Right: 0.00	Distance	100.00	Front axle	Left: 0.00, Right: 0.00	Distance	100.00
Rear axle	Left: 0.00, Right: 0.00	Distance	100.00	Rear axle	Left: 0.00, Right: 0.00	Distance	100.00
Total weight				Total weight			
1234 kg				1234 kg			

Brake and shock absorber report

Car				Car			
Model:	2017 Toyota Aygo	Year:	2017	Model:	2017 Toyota Aygo	Year:	2017
Registration:	2017	Manufacturer:	TOYOTA	Registration:	2017	Manufacturer:	TOYOTA
Test date:	25/09/2026	Test time:	11:54	Test date:	25/09/2026	Test time:	11:54
Test results				Test results			
Side-slip test				Side-slip test			
Front axle	+ 1.00%	Rear axle	+ 2.00%	Front axle	+ 1.00%	Rear axle	+ 2.00%
Shock absorber test				Shock absorber test			
Front axle	Left: 0.00, Right: 0.00	Distance	100.00	Front axle	Left: 0.00, Right: 0.00	Distance	100.00
Rear axle	Left: 0.00, Right: 0.00	Distance	100.00	Rear axle	Left: 0.00, Right: 0.00	Distance	100.00
Brake test				Brake test			
Front axle	Left: 0.00, Right: 0.00	Distance	100.00	Front axle	Left: 0.00, Right: 0.00	Distance	100.00
Rear axle	Left: 0.00, Right: 0.00	Distance	100.00	Rear axle	Left: 0.00, Right: 0.00	Distance	100.00
Total weight				Total weight			
1234 kg				1234 kg			

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:

2017302467

DATE

25/09/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



ENGINE 1



Front chassis



Rear chassis



Spare Wheel Accessories



Interior boot lock plastic tri



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Water level



Water level



Headlight Right



Headlight Left



Under bonnet insulation cover



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Seat Front Right



Clutch Pedal Rubber



Gear Lever Dust Boot



Heater control



Steering Wheel Trim



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Front Fender Right



Side Mirror Right



Door Front Right



Door Rear Right



Rear Fender Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730




CONDITION REPORT




Report No:
2017302467
DATE
25/09/2026




Fuel Flap



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



C • Pillar Left



Seat Front Left



Sill Panel Left



Bonnet



Roof



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:

2017302467

DATE

25/09/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



Tail Light Right



Boot Carpet



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Inner Boot Floor Pan and Spare Wheel Well




Boot Lid / Hatch Door Rubbers



Front Fender Right / Inner Tray



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Rim Front Left



Shock Absorber Front Left



Fog Light Front Right



Fog Light Front Left



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Front Bumper



Rim Rear Left



Rim Rear Right



Engine to silencer pipe



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Tyre Front Right



Tyre Front Left



Tie Rod End right



Chassis



Chassis



Mounting Rubber(s) Rear Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Mounting Rubber(s) Rear Axle Left



Tyre Rear Right



Tyre Rear Left



Inner Boot Floor Pan and Spare Wheel Well



Shock Absorber Mounting Front Left



Shock Absorber Mounting Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730



CONDITION REPORT



Report No:
2017302467
DATE
25/09/2026



Switch Electrical Window Winder front left



Sun Visor Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MJB29BTX00122730