

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



#### Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/12/2023		M57 Pretoria Road - 1619
Inspection Date	28/12/2023		Kempton Park - GT

#### Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	KSF759MP
Model	MAGNITE	Register Number	
VIN	MDHFBADD0Z0007449	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/10/2023
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	18,070 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

#### Vehicle Options & Accessories

##### Items

#### VEHICLE INSPECTION

Damage	Repair Way
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair



## Brakes

### Brake Test Results

	Left	Right	Axe Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [kN]	Braking Force [kN]		
Front	2.4	2.63	-	-
Rear	1.45	1.4	-	-
Emergency / Parking	1.3	0.96	-	-

## Tyres and Rims

### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60R16	89V	Ceat	Radial	V	2522	3 mm
Front Right	195/60R16	89V	Ceat	Radial	V	2422	3 mm
Rear Left	195/60R16	89V	Ceat	Radial	V	2522	2 mm
Rear Right	195/60R16	89V	Ceat	Radial	V	2422	3 mm

\* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

## Inspection Conditions

No Test Drive

Rain at time of inspection

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. SHOCK ABSORBER TEST NOT PERFORMED.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



## CONDITION REPORT

Report No: 2016212721

VIN: MDHFBADD0Z0007449

DATE

28/12/2023



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



## CONDITION REPORT

Report No: 2016212721

DATE  
28/12/2023

VIN: MDHFBADD0Z0007449

5 / 9

VIN: MDHFBADD0Z0007449

6 / 9




RF TYRE TREAD




LICENSE DISC




VIN PLATE OR STICKER



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3




## CONDITION REPORT

Report No: 2016212721

DATE  
28/12/2023

VIN: MDHFBADD0Z0007449

7 / 9



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ENGINE 1



ADDITIONAL 10



ADDITIONAL 11



## CONDITION REPORT

Report No: 2016212721

DATE  
28/12/2023

VIN: MDHFBADD0Z0007449

9 / 9



Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left



## CONDITION REPORT

Report No: 2016212721

DATE  
28/12/2023



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Front Right




Door Rear Right



## CONDITION REPORT

Report No: 2016212721

DATE  
28/12/2023





## CONDITION REPORT

Report No: 2016212721

DATE  
28/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)