



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/08/2025		M57 Pretoria Road - 1619
Inspection Date	29/08/2025		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	LJ55ZVGP
Model	MAGNITE TURBO 1.0T ACENTA PLUS 5-DR CVT [2022-2024]	Register Number	
VIN	MDHFBADD0Z0016332	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/10/2025
Color	RED	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	44,352 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025

**Damage**

Hoses Oil Leak	Repair
Seat Front Left Dirty	Repair
Seat Rear Dirty	Repair
Front Bumper Damaged	Repair
C • Pillar Left Paintwork • Scratched	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Windscreen Cracked	Replace
Spare Tyre Damaged	Replace
Warning lights illuminated on dashboard	Repair

**Repair Way****Brakes****Brake Test Results**

	Left	Right	Axe Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	2.11	2.44	-	
Rear	1.58	1.67	-	
Emergency / Parking	1.02	1.04	-	

**Tyres and Rims****Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60 R16	89V	Ceat	Secure drive	V	0423	6 mm
Front Right	195/60 R16	89V	Ceat	Secure drive	V	0423	3 mm
Rear Left	195/60 R16	89V	Ceat	Secure drive	V	0523	5 mm
Rear Right	195/60 R16	89V	Ceat	Secure drive	V	0423	5 mm
Spare	205/60 R16	96H	Davanti	DX390	V	2422	0 mm

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025

### **Diagnostic**

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C1082:87	NO SEQUENTIAL GEARBOX MLTIPLEX SIG 2.DEF	

### **Inspection Conditions**

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### **Comments**

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine bay dirty.  
Interior: Vehicle interior dirty and some panels scratched  
Body • Exterior: Minor dents and scratches on some body panels  
Tyres and Rims: Spare wheel regrooved.

### **Concluding Remarks**

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### **Technician**

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



# CONDITION REPORT

Report No:  
2016996317  
DATE  
29/08/2025



Brake and shock absorber report

Diagnostic report page 1

Diagnostic report page 2



#### FRONT RIGHT CORNER



REAR LEFT CORNER



## INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chase



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



Door Front Right



Door Front Right



Door Rear Right



Door Rear Right



Seat Rear



C • Pillar Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



Rear Fender Left



Rear Fender Left



Seat Front Left



Front Fender Left



Front Fender Left



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



Front Bumper



Front Bumper



Windscreen



Front Fender Right



Spare Tyre



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332



## CONDITION REPORT



Report No:  
2016996317  
DATE  
29/08/2025



Water level



Inner Boot Floor Pan and Spare Wheel Well



Water level



Hoses

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MDHFBADD0Z0016332