



CONDITION REPORT



Report No:
2017301041
DATE
18/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	18/09/2026		M57 Pretoria Road - 1619
Inspection Date	18/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	LGK065MP
Model	MAGNITE 1.0 ACENTA 5-DR AMT [2024-ON]	Register Number	
VIN	MDHFBADD0Z0032299	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	RED	Power / Displacement	
Year Model	2025	Paint Finish	TWO COAT UNI
Km Reading	13,785 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:

2017301041

DATE

18/09/2026

Damage

Repair Way

Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Door Panel Front Left Dirty	Repair
Door Panel Rear Left Dirty	Repair
Door Panel Rear Right Dirty	Repair
Bonnet Dented	Repair
Front Fender Left Defective	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Defective	Repair
Door Front Right Dented	Repair
Door Rear Left Defective	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Chipmarks	Repair
Rear bumper Paintwork • Chipmarks	Repair
Rim Rear Left Defective	Repair
Warning light illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.96	3.01	-	
Rear	1.79	1.69	-	
Emergency / Parking	1.2	0.84	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60 R16	89V	Ceat	Secure drive	V	4124	4 mm
Front Right	195/60 R16	89V	Ceat	Secure drive	V	4124	4 mm
Rear Left	195/60 R16	89V	Ceat	Secure drive	V	4124	5 mm
Rear Right	195/60 R16	89V	Ceat	Secure drive	V	4124	5 mm
Spare	195/60 R16	89V	Ceat	Secure drive	V	4124	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:

2017301041

DATE

18/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P060A:49	ECU 1.DEF	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Minor dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:
2017301041
DATE
18/09/2026

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report page 1

[illegible]

Diagnostic report page 2

[illegible]

Diagnostic report page 3



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:

2017301041

DATE

18/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:

2017301041

DATE

18/09/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:

2017301041

DATE

18/09/2026



Spare Wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Fron chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:


2017301041

DATE

18/09/2026



Oil cap and dipstick



Seat Front Right



Door Front Right



Door Rear Right



Door Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT




Report No:

2017301041

DATE

18/09/2026



Rear fender right



Seat Rear



Rear bumper



Rear bumper



Boot Lid / Hatch door



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:


2017301041

DATE

18/09/2026




Door Rear Left



Door Rear Left



Seat Front Left



Door Front Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:

2017301041

DATE

18/09/2026



Front Fender Left



Bonnet



Water level



Rim Rear Left



Water level



Door Panel Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299



CONDITION REPORT



Report No:
2017301041
DATE
18/09/2026



Door Panel Rear Left



Door Panel Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHFBADD0Z0032299