

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/02/2024		M57 Pretoria Road - 1619
Inspection Date	07/02/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	DKP643L
Model	MICRA	Register Number	
VIN	MDHFBUK13Z0516881	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	07/02/2024
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	238,956 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Wiring Defective	Repair
Caps Missing	Replace
Fan Belt Defective	Replace
Battery clamps Defective	Repair
Air cleaner Defective	Repair
Heater control Defective	Replace
Windscreen Wiper Missing	Replace
Tail Light Left Defective	Replace
Headlight Left Defective	Replace
Headlight Right Defective	Replace
Seat Front Right Damaged	Repair
Seat Rear Defective	Repair
Hood Lining Defective	Repair
Door Sealing Rubber Front Right Damaged	Replace
Carpet Front Damaged	Repair
Boot Carpet Damaged	Replace
Steering Wheel Trim Defective	Repair
Number Plate Front Cracked	Replace
Number Plate Rear Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
B • Pillar Left Paintwork • Scratched	Repair
B • Pillar Right Paintwork • Scratched	Repair
C • Pillar Right Dented	Repair
Front Fender Left Paintwork • Discoloured	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Dented	Repair

Damage	Repair Way
Door Front Right Damaged	Repair
Door Rear Left Dented	Repair
Door Rear Right Damaged	Repair
Doorstopper Front Left Defective	Replace
Doorstopper Front Right Defective	Replace
Doorstopper Rear Left Defective	Replace
Doorstopper Rear Right Defective	Replace
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Rocker Panel Right Dented	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle right Defective	Replace
Wheel bearing Front Left Loose / Excessive Play	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Defective	Replace
Spare Tyre Worn	Replace
Rim Front Right Dented	Repair
Rim Rear Left Dented	Repair
Rim Rear Right Dented	Repair
Rim Spare Wheel Dented	Repair
Main Beam Left Dented	Repair
Chassis Dented	Repair
Sub Frame Dented	Repair
Gearbox Mountings Welded	Replace
Gearbox Damaged	Repair
Radiator Cradle Damaged	Replace
Engine management light illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.53	2.53	-	
Rear	1.63	1.9	-	
Emergency / Parking	1.39	1.48	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/50 R15	82V	Dunlop	Sp-Sport	V	1316	0 mm
Front Right	195/50 R15	82V	Dunlop	Sp-Sport	V	1319	0 mm
Rear Left	195/50 R15	82V	Symmetry	SY201	V	4821	5 mm
Rear Right	195/50 R15	82V	Symmetry	SY201	V	1822	5 mm
Spare	T115/70 D14	88M	Falken	Temporary	V	3913	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P0132	H02S1(B1)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: VEHICLE HAS NO LICENSE DISC
Engine Compartment: Engine bay dirty.Brake fluid level ok.Battery loose.Corrosion on battery box and clamps.Oil sump dented.Aircon condenser loose.Radiator and Aircon condenser misaligned.
Interior: Vehicle interior d

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

VIN: MDHFBUK13Z0516881

7 / 21



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC

VIN: MDHFBUK13Z0516881

8 / 21



VIN PLATE OR STICKER



ENGINE 1



Rear chassis



Front chassis



Oil cap and dipstick



Manual Transmission

VIN: MDHFBUK13Z0516881

10 / 21

VIN: MDHFBUK13Z0516881
11 / 21



Heater control



Doorstopper Front Right



Seat Front Right



Door Sealing Rubber Front Right



Sill Panel Right



Doorstopper Rear Right


VIN: MDHFBUK13Z0516881

12 / 21



VIN: MDHFBUK13Z0516881

13 / 21



VIN: MDHFBUK13Z0516881

14 / 21



Front Fender Right



Rear bumper

VIN: MDHFBUK13Z0516881
15 / 21



Rear bumper



Tail Light Left



Boot Lid / Hatch door



Windscreen Wiper

VIN: MDHFBUK13Z0516881

16 / 21



Rear Fender Left



Door Rear Left

K3Z0516881
17 / 21



Doorstopper Rear Left



Sill Panel Left



Seat Rear



B • Pillar Left

VIN: MDHFBUK13Z0516881

18 / 21



Sill Panel Left



Doorstopper Front Left VIN: MDHFBUK13Z0516881



Front Fender Left



Headlight Left



Headlight Right



Front Bumper

VIN: MDHFBUK13Z0516881

20 / 21



Front Bumper



Bonnet



Number Plate Front



Number Plate Rear

VIN: MDHFBUK13Z0516881
21 / 21



Door Front Left



Hood Lining



Steering Wheel Trim



B • Pillar Right



Water level



Boot Carpet



Boot Carpet



Boot Carpet



Spare Tyre



Rim Spare Wheel



Inner Boot Floor Pan and Spare Wheel Well



Control Arm Bush(es) Front Axle Right



Fan Belt



Rocker Panel Right



Tyre Rear Left




Wheel bearing Front Left



Control Arm Bush(es) Front Axle Left



Tyre Front Left



Tyre Front Left



Tyre Front Right



Rim Front Right



Brake disc 1. Axle right



Radiator Cradle



Radiator Cradle



Radiator Cradle



Sub Frame



Gearbox Mountings



Chassis



Mounting Rubber(s) Rear Axle Left



Mounting Rubber(s) Rear Axle Right



Rim Rear Left



Rim Rear Right



Main Beam Left



Gearbox



Caps



Engine Wiring



Air cleaner



Battery clamps



Carpet Front



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za