



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/07/2025		M57 Pretoria Road - 1619
Inspection Date	30/07/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	JF73NHGP
Model	KWID	Register Number	
VIN	MEEBBA007K7677937	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2022
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	137,839 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories**Items****VEHICLE INSPECTION**

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Switch Electrical Window Winder front right Defective	Repair
Tail Light Left Cracked	Replace
Headlight Left Cracked	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Torn / Cut	Repair
Door Panel Front Right Damaged	Repair
Door Handle Front Right Damaged	Repair
Door Handle Rear Left Damaged	Replace
Parcel Tray Missing	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Damaged	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Windscreen Chipped	Replace
Control Arm Bush(es) Front Axle Left Damaged	Replace
Control Arm Bush(es) Front Axle Right Damaged	Replace
Tyre Front Left Excessive Wear & Tear	Replace
Tyre Front Right Excessive Wear & Tear	Replace
Tyre Rear Left Excessive Wear & Tear	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Excessive Wear & Tear	Replace
Rim Front Right Dented	Repair
Main Beam Left Damaged	Repair
Engine to silencer pipe Welded	Repair
Silencer Welded	Repair
Gearbox Mountings Cracked	Replace
foreign substance on oil cap	Repair
exhaust system leak	Repair
Warning lights illuminated	Repair
Drive electric window not working	Repair

Brakes

Brake Test Results

	Left	Right	Axe Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	1.4	1.2	-	
Rear	0.9	0.9	-	
Emergency / Parking	0.7	0.8	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	155/70R13	75T	Farroad	FRD	V	2620	0 mm
Front Right	155/70R13	75T	Goodyear	duragrip	V	0000	0 mm
Rear Left	155/80R13	79T	Jk tyre	Ultima	V	2619	0 mm
Rear Right	155/80R13	79T	jk tyre	Ultima	V	2619	0 mm
Spare	155/80R13	79T	Dunlop	Sport	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	RADIO	DTC934262	UNIT LOCKED COMPUTER LOCKED	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT




Report No:
2016963111
DATE
30/07/2025

Car		License pl. no.: 377854P		Car	
Model:	Year:	Color:	Length:	Model:	Year:
Opener, abs:		Wheels:	Width:	Manufacturer:	2014
Brake system:		Wheels:	Height:	Model name:	RENAULT KWID
Test date:	2025/07/30	Test time:	10:00	Vehicle ID:	MEEBBA007K7677937
Test location:	D40	Test place:	VIN:		
Test results					
Shock absorber test			Results		
Front side	> 10 %	Rear side	> 10 %	Front side	> 10 %
Front side	0.2%	Rear side	0.2%	Front side	0.1%
Front side	> 2.0%	Rear side	> 2.0%	Front side	> 0.5%
Front side	0.0%	Rear side	0.0%	Front side	0.0%
Basic test					
Front side	0.0%	Rear side	0.0%	Front side	0.0%
Parking brake	0.74 KN	Front side	0.85 KN	Parking brake	0.74 KN
Parking brake	0.74 KN	Rear side	0.76 KN	Parking brake	0.74 KN
Final evaluation score	83 %	Final evaluation score	83 %	Final evaluation score	83 %
Deceleration service brake	23 %	Total weight	242 kg	Deceleration service brake	23 %
Deceleration parking brake	23 %			Deceleration parking brake	23 %


Shock and brake report




Diagnostic test



Diagnostic test



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LR TYRE TREAD



LF TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Rear end



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



CHASSIS



Dipstick



Oil cap



Expansion bottle



L/F headlight clips broken



Warning lights illuminated

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Sparewheel



L/F fender liner missing



Headlight Left



Engine Wiring



Main Beam Left



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Seat Front Left



Switch Electrical Window Winder front right



Door Handle Rear Left



Seat Rear



Windscreen



Door Handle Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Door Rear Right



Boot Lid / Hatch door



Boot Lid / Hatch door



Spare Tyre



Parcel Tray



Boot Lid / Hatch door



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Tail Light Left



Rear Fender Left



Door Rear Left



Front Fender Left



Bonnet



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Control Arm Bush(es) Front Axle Right



Front Fender Right



Front Bumper



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Tyre Front Left



Control Arm Bush(es) Front Axle Left



Tyre Rear Left



Tyre Rear Right



Rear Fender Right



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Main Beam Left



Rim Front Right



Engine



Engine



Engine



Gearbox Mountings

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937



CONDITION REPORT



Report No:
2016963111
DATE
30/07/2025



Engine to silencer pipe



Silencer



Silencer



Silencer



Engine to silencer pipe



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA007K7677937