

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/09/2024		M57 Pretoria Road - 1619
Inspection Date	09/09/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	JX87TLGP
Model	KWID	Register Number	
VIN	MEEBBA00900744849	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	81,066 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Radio/CD/USB Defective	Repair
Parcel Tray Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
B • Pillar Right Paintwork • Scratched	Replace
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rocker Panel Left Dented	Repair
Roof Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Caliper 1. Axle left Sweat	Repair
Caliper 1. Axle right Sweat	Repair
Chassis Dented	Repair
Tyres and rims	Spare wheel missing
Engine	Engine bay dirty
Engine	Firewall insulation cover damaged
Engine	Brake fluid reservoir defective.
Tyres and rims	Front and rear hubcaps scratched.
Body and Exterior	Minor dents and scratches on some body panels
Interior	Vehicle interior dirty and some panels scratched

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.85	1.63	-	
Rear	1.26	1.39	-	
Emergency / Parking	0.85	1.14	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70 R14	81T	Ceat	Fuelsmart	V	3720	4 mm
Front Right	165/70 R14	81T	Ceat	Fuelsmart	V	3820	4 mm
Rear Left	185/70 R14	81T	Ceat	Fuelsmart	V	3820	2 mm
Rear Right	185/70 R14	81T	Ceat	Fuelsmart	V	3820	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC033531	ENGINE SPEED SENSOR SIGNAL NO SIGNAL	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Brake fluid reservoir



Front chassis



Rear Chassis



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Radio/CD/USB



Windscreen



B • Pillar Right



Door Front Right



Boot Lid / Hatch door



Rear Fender Left



Door Rear Left



Door Front Left



Front Bumper



Front Bumper



Bonnet



Roof



Parcel Tray



Water level



Rocker Panel Left



Caliper 1. Axle left



Caliper 1. Axle right



Chassis



CONDITION REPORT

Report No: 2016524714

DATE
09/09/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za