



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 25/07/2025 | | M57 Pretoria Road - 1619 |
| Inspection Date | 25/07/2025 | | Kempton Park - GT |

Vehicle Data

| | | | |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC |
| Manufacturer | RENAULT | Registration Number | LB77HTGP |
| Model | TRIBIER | Register Number | |
| VIN | MEERBC00500072377 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 28/02/2025 |
| Color | RED | Power / Displacement | |
| Year Model | | Paint Finish | TWO COAT METALLIC |
| Km Reading | 148,427 KM | Fuel | PETROL |
| Cab / Body Type | STATION WAGON | Transmission | MANUAL |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



Damage

Repair Way

| | |
|-----------------------------------|---------|
| Front Bumper Damaged | Repair |
| Bonnet Damaged | Repair |
| Front Fender Left Damaged | Repair |
| Front Fender Right Damaged | Repair |
| Rear Fender Right Damaged | Repair |
| Door Front Left Damaged | Repair |
| Door Front Right Damaged | Repair |
| Door Rear Left Damaged | Repair |
| Door Rear Right Damaged | Repair |
| Boot Lid / Hatch door Damaged | Repair |
| Rear bumper Damaged | Repair |
| Shock Absorber Rear Left Damaged | Replace |
| Shock Absorber Rear Right Damaged | Replace |
| Tyre Rear Left Worn | Replace |
| Spare Tyre Worn | Replace |
| Engine Performance Insufficient | Repair |
| Engine Noise Idling / Hunting | Repair |

Brakes

Brake Test Results

| | Left | Right | | |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s ²] |
| Front | 1.94 | 1.62 | - | |
| Rear | 1.24 | 1.16 | - | |
| Emergency / Parking | 0.95 | 0.79 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|----------|-------|-----------------|------------------|
| Front Left | 175/65R14 | 82H | Royal | Radial | V | 2920 | 2 mm |
| Front Right | 175/65R14 | 88H | Apollo | Radial | V | 4018 | 1 mm |
| Rear Left | 185/65R14 | 82H | Hankook | Radial | V | 5211 | 0 mm |
| Rear Right | 185/60R14 | 82H | Continental | Contieco | V | 2421 | 1 mm |
| Spare | 155/80R13 | 79T | Sava | Radial | V | 0000 | 0 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377

**CONDITION REPORT**

Report No:
2016958188
DATE
25/07/2025

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. VEHICLE STRUGGLES TO START
Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Vehicle body in poor condition.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEERBC00500072377




CONDITION REPORT




Report No:
2016958188
DATE
25/07/2025



Brake test.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



90 DEGREE LEFT



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



Water level




Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



Door Rear Left




Rear bumper



Rear bumper



Boot Lid / Hatch door



Front Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377



CONDITION REPORT



Report No:
2016958188
DATE
25/07/2025



Door Front Right



Door Rear Right



Tyre Rear Left



Shock Absorber Rear Left



Shock Absorber Rear Right



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500072377