



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/04/2025		M57 Pretoria Road - 1619
Inspection Date	30/04/2025		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	KMJ344MP
Model	AVANZA 1.5 SX MPV [2019-2022]	Register Number	
VIN	MHKM5FA2N0K013298	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2026
Color	SILVER	Power / Displacement	
Year Model	2020	Paint Finish	TWO COAT METALLIC
Km Reading	338,572 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION



Damage	Repair Way
Bonnet stay and shocks Missing	Replace
Central Air Vent Damaged	Repair
Engine Management Lights Set	Repair
Headlight Left Damaged	Repair
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Sun Visor Left Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Damage	Repair Way
Sill Panel Left Damaged	Repair
Caliper 1. Axle left Leak	Replace
Caliper 1. Axle right Leak	Repair
Wheel Cylinder / Caliper 2. Axle left Leak	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Shock Absorber Front Left Worn	Replace
Shock Absorber Front Right Worn	Replace
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Tyre Front Left Damaged	Replace
Differential Oil Leak	Replace

**Brakes****Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [kN]	Braking Force [kN]		
Front	1.97	2.23	-	
Rear	1.25	0.16	-	
Emergency / Parking	0	0	-	

**Tyres and Rims****Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	88H	Autogrip	Radial	V	2424	2 mm
Front Right	185/70R14	88H	Autogrip	Radial	V	2424	2 mm
Rear Left	185/70R14	88H	Voyager	Radial	V	4222	3 mm
Rear Right	185/70R14	88H	Voyager	Radial	V	4422	3 mm

\* Tyre Legend: V=Virgin, R=Recap

**Diagnostic**

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C1238	ABNORMAL CYCLE OF RR WHEEL	

**Inspection Conditions**

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

**Comments**

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 4 DTC'S AT TIME OF TESTING SEE DTC REPORT. Body • Exterior: Minor dents and scratches to some body panels. Signs of stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Vehicle body in poor condition. Repair work done to vehicle below standard.

Axle and Suspension: rear trailing arm bushes worn.

**Concluding Remarks**

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE  
 DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksdorp, Pretoria, 0200  
 Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025**Technician**

Werner Laubscher

This document was created electronically and is valid without signature.

## General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298




## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Brake test



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT


Report No: 2016859990

DATE  
30/04/2025

ENGINE 1



Undercarriage front.



Undercarriage rear.




Oil cap and dipstick.



Bonnet stay and shocks



Headlight Left



DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Front Bumper



Bonnet



Front Bumper



Front Fender Left



Rear Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Front Fender Right



Rear Fender Right



Seat Front Right



Seat Front Left



Central Air Vent



Engine Management Lights

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Sun Visor Left



Sill Panel Left



Headlight Right



Wheel Cylinder / Caliper 2. Axle left



Caliper 1. Axle left



Caliper 1. Axle right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right



Shock Absorber Front Left



Shock Absorber Front Right



Differential



Tyre Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298



## CONDITION REPORT

Report No: 2016859990

DATE  
30/04/2025

Water level

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MHKM5FA2N0K013298