



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	05/01/2024		M57 Pretoria Road - 1619
Inspection Date	05/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	FH975MGP
Model	AVANZA	Register Number	
VIN	MHKM5FB2N0K000317	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2020
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	133,950 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Wiring Defective	Repair
Windscreen Wiper Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Hood Lining Damaged	Repair
Door Panel Rear Right Defective	Repair
Boot Panel Left Defective	Repair
Boot Panel Right Defective	Repair
Steering Wheel Trim Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Grill Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
B • Pillar Right Dented	Repair
C • Pillar Right Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Rear Fender Left / Inner Tray Dented	Repair
Rear Fender Right / Inner Tray Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Doorstopper Front Right Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5FB2N0K000317

1 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Damage	Repair Way
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Rocker Panel Left Paintwork • Scratched	Repair
Rocker Panel Right Dented	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle left Defective	Replace
Brake disc 1. Axle right Defective	Replace
Shock Absorber Rear Left Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Chassis Dented	Repair
Belly plates Damaged	Repair
Gearbox Oil Sweat	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace

Brakes**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	2.33	1.93	-	
Rear	2.33	2.4	-	
Emergency / Parking	1.48	1.45	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70 R14	88T	Dunlop	Sp-Sport	V	4017	3 mm
Front Right	185/70 R14	88T	Dunlop	Sp-Sport	V	4017	3 mm
Rear Left	185/70 R14	88T	Dunlop	Sp-Sport	V	1317	4 mm
Rear Right	185/70 R14	88T	Dunlop	Sp-Sport	V	2017	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	EFI	P0504	STOP LAMP SWITCH SYSTEM FAULT	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SHOCK ABSORBER TEST COULD NOT BE PERFORMED.Engine Compartment: Engine bay dirty.Brake fluid level ok.Corrosion on battery box.
 Li

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

VIN: MHKMEF20162003793

Report No: 20162003793

2 / 17

DATE

05/01/2024

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016218793

VIN: MHKM5FB2N0K000317

DATE

05/01/2024



Brake test report



Front chassis



Rear chassis



Diagnostic report page 1



Diagnostic report page 2



Oil cap and dipstick



CONDITION REPORT

Report No: 2016218793

DATE

VIN: MHKM5FB20510092024

05/09/2024

4 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218793

DATE

05/01/2024

VIN: MHKM5FB2NOK000317

5 / 17



Automatic Transmission



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

6 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

7 / 17



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

8 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front Bumper



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

10 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Front Bumper



Bonnet



Front Fender Left



Windscreen Wiper



Seat Front Left



Seat Rear (2. Row)



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

12 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Boot Panel Right



Boot Panel Left



Seat Rear



Sill Panel Left



Rear bumper



Rear bumper



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

14 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Rear bumper



Boot Lid / Hatch door



C • Pillar Right



Seat Rear



Hood Lining



Door Panel Rear Right



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

VIN: MHKM5FB2N0K000317

16 / 17



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Hood Lining



Seat Front Right

VIN: MHKMSFB2NOK000317
17 / 17

B • Pillar Right



Windscreen



Steering Wheel Trim



Rear bumper



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Boot Lid / Hatch door



Boot Panel Left



Boot Panel Right



Door Front Right



Door Rear Right



Rear Fender Right



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Rear Fender Left



Door Rear Left



Door Front Left



Roof



B • Pillar Right



Water level



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Front Fender Right



Control Arm Bush(es) Front Axle Right



Rocker Panel Right



Rocker Panel Left



Control Arm Bush(es) Front Axle Left



Brake disc 1. Axle left



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Brake disc 1. Axle right



Belly plates



Shock Absorber Rear Left



Rear Fender Left / Inner Tray



Rear Fender Right / Inner Tray



Chassis



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

Gearbox



Engine Wiring



Headlight Left



Headlight Right



Grill



Doorstopper Front Right



CONDITION REPORT

Report No: 2016218793

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za