



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/09/2026		M57 Pretoria Road - 1619
Inspection Date	29/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MAZDA	Registration Number	KWF046MP
Model	MAZDA2 1.5 DYNAMIC 5-DR [2017-2020]	Register Number	
VIN	MM6DJ2HA6HW300800	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2026
Color	GREY	Power / Displacement	
Year Model	2017	Paint Finish	TWO COAT UNI
Km Reading	129,143 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026

Damage

Repair Way

Engine Wiring Damaged	Repair
Under bonnet insulation cover Damaged	Repair
Radio/CD/USB Damaged	Replace
Windscreen Wiper Missing	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Parcel Tray Missing	Replace
Boot Panel Left Damaged	Repair
Boot Panel Right Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Chipmarks	Repair
Side Mirror Right Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Defective	Repair
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Right / Inner Tray Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Chipmarks	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Roof Dented	Repair
Windscreen Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Rim Front Left Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Main Beam Left Damaged	Repair
Belly plates Damaged	Replace
Radiator Cradle Damaged	Replace
Warning light illuminated on dashboard	Repair
Rear left interior sill panel plastic trim damaged	Replace
Aircon condenser dented	Repair
Radiator and Aircon condenser misaligned	Repair
Rear windshield wiper arm missing	Replace
Front left and right headlight lenses faded	Repair

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.42	2.43	-	
Rear	1.87	1.87	-	
Emergency / Parking	1.41	1.36	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	92T	Sumitomo	BC100	V	3225	3 mm
Front Right	185/65 R15	92T	Sumitomo	BC100	V	1825	3 mm
Rear Left	185/65 R15	92T	Sumitomo	BC100	V	3225	4 mm
Rear Right	185/65 R15	92T	Sumitomo	BC100	V	3225	4 mm
Spare	T125/70 D15	95M	Falken	Temporary	V	4416	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS(ANTI-LOCK BRAKE SYSTEM)	U0401:00-60	INVALID DATA RECEIVED FROM ELECTRONIC CONTROL MODU	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. VEHICLE INTERIOR DIRTY AND PANELS SCRATCHED / DENTS AND SCRATCHES ON BODY PANELS / SIGNS OF HAIL DAMAGE ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT AND REAR OF VEHICLE / BODY PANELS MISALIGNED / BOTTOM OF ENGINE AND GEARBOX FULLY COVERED / VEHICLE UNDERCARRIAGE DIRTY.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800

**CONDITION REPORT**

Report No:
2017304709
DATE
29/09/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026



ENGINE 1



Front chassis




Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT




Report No:

2017304709

DATE _____

29/09/2026



LR TYRE TREAD




RR TYRE TREAD




Spare Wheel and Accessories

[illegible]

Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026



Rear left interior sill panel




Aircon condenser



Radio/CD/USB



Seat Front Right



Seat Rear



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026



Front Fender Right



Door Front Right



Door Front Right



Side Mirror Right



Rim Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026



Door Rear Right



Rear Fender Right



Rear bumper



Roof



Windscreen Wiper



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026



Door Rear Left



Door Rear Left



Rim Rear Left



Seat Rear



Seat Front Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026



Door Front Left



Front Fender Left



Side Mirror Left



Windscreen



Rim Front Left



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800




CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026



Bonnet



Front Fender Right / Inner Tray



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:

2017304709

DATE

29/09/2026



Belly plates



Radiator Cradle



Main Beam Left



Rear Fender Right / Inner Tray



Inner Boot Floor Pan and Spare Wheel Well



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026



Boot Panel Left



Boot Panel Right



Under bonnet insulation cover



Water level



Engine Wiring



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MM6DJ2HA6HW300800



CONDITION REPORT



Report No:
2017304709
DATE
29/09/2026



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6DJ2HA6HW300800