



CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HONDA	Registration Number	KW40TGGP
Model	BALLADE 1.5 COMFORT AT [2011-2014]	Register Number	
VIN	MRHGM2640DP050192	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2026
Color	WHITE	Power / Displacement	
Year Model	2013	Paint Finish	TWO COAT UNI
Km Reading	276,510 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:

2017304198

DATE

30/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Engine Management Lights Set	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Seat Front Right Damaged	Repair
Seat Rear Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
A • Pillar Right Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Gearbox Oil Leak	Repair
Engine Performance Insufficient	Repair
Engine Noise Idling / Hunting	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.1	2.16	-	
Rear	1.9	1.88	-	
Emergency / Parking	1.32	1.21	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R15	84H	Durun	Radial	V	4523	0 mm
Front Right	175/65R15	84H	Durun	Radial	V	4523	0 mm
Rear Left	175/65R15	84H	Durun	Radial	V	4523	1 mm
Rear Right	175/65R15	84H	Durun	Radial	V	4523	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	SRS	85-61	NO SIGNAL FROM THE ODS UNIT	PERMANENT DTC

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Foreign substance on oil filler cap. vehicle has a excessive oil leak. Battery loose. Electrical Components and Instruments: vehicle struggles to start. vehicle electronics malfunctioning.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT




Report No:


2017304198

DATE _____

30/09/2026




Brake test.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:

2017304198

DATE

30/09/2026




Front Bumper



Bonnet




Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:

2017304198

DATE

30/09/2026



Rear Fender Right




A • Pillar Right



Roof



Engine Management Lights



Tyre Front Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192



CONDITION REPORT



Report No:

2017304198

DATE

30/09/2026



Engine



Engine



Gearbox



Seat Front Right



Seat Rear



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192




CONDITION REPORT



Report No:
2017304198
DATE
30/09/2026



Tail Light Right



Service Brake Performance Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MRHGM2640DP050192