



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	21/02/2024		M57 Pretoria Road - 1619
Inspection Date	21/02/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HONDA	Registration Number	HDH719MP
Model	CR-V	Register Number	
VIN	MRHRM1750EP000027	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2021
Color	BROWN	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	43,303 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Headlight Left Scratched	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Grill Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Engine to silencer pipe Welded	Replace
Steering Malfunction	Repair
Body and Exterior	Dents and scratches on some body panels.
Body and Exterior	Some body panels misaligned
Body and Exterior	Spray work and stone chips on some body panels.
Undercarriage	Vehicle undercarriage dirty
Tyres and Rims	Alloy rims scratched.
Engine	Engine bay dirty. Brake fluid level ok.
Electrical components and Instruments	Vehicle electronics malfunctioning
Warning light illuminated on dashboard	Repair
Interior	Vehicle interior dirty.



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

Brakes

Brake Test Results

Brake efficiency tested during road test.

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.85	2.92	-	
Rear	2.54	2.63	-	
Emergency / Parking	1.47	2.43	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/65 R17	102T	Michelin	Latitude	V	0813	4 mm
Front Right	225/65 R17	102T	Michelin	Latitude	V	0813	4 mm
Rear Left	225/65 R17	102T	Michelin	Latitude	V	0813	5 mm
Rear Right	225/65 R17	102T	Michelin	Latitude	V	0813	5 mm
Spare	225/65 R17	102T	Michelin	Latitude	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/TCS/VSA	61-12	MODULATOR-CONTROL UNIT POWER SOURCE CIRCUIT(IG)LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT


VIN: RAHRN172016000249

Report No: 2016000249

2 / 9

DATE


21/02/2024



Brake and shock absorber report



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016276249

VIN: MRHRM1750EP000027

DATE

21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276249

DATE

VIN: MRHRM1729500292024

4 / 9



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

VIN: MRHRM1750EP000027

5 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

VIN: MRHRM1750EP000027

6 / 9



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

VIN: MRHRM1750EP000027

7 / 9



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

VIN PLATE OR STICKER

VIN: MRHRM1750EP000027
8 / 9

Front chassis



Rear chassis



Oil cap and dipstick



Manual Transmission



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

VIN: MRHRM1750EP000027

9 / 9



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

Side Mirror Left



Front Bumper



Front Bumper



Bonnet



Headlight Left



Rear bumper



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

Rear bumper



Door Front Right



Door Rear Right



Rear Fender Right



Door Rear Left



Door Front Left



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276249

DATE
21/02/2024

Front Fender Left



Grill



Engine to silencer pipe



Water level



**CONDITION REPORT**

Report No: 2016276249

DATE
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za