



CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	16/09/2026		M57 Pretoria Road - 1619
Inspection Date	16/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	KIA	Registration Number	LM80LLGP
Model	SONET	Register Number	
VIN	MZBFC814TPN333249	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	69,418 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Radio/CD/USB Defective	Repair
Windscreen Wiper Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Door Sealing Rubber Front Right Damaged	Replace
Boot Carpet Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Tyre Rear Right Damaged	Replace
Jack Missing	Replace
Wheel Spanner Missing	Replace
Vehicle license disk missing	Replace
Spare Wheel missing	Replace
Deceleration parking brake defective	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.36	3.07	-	
Rear	1.19	2.34	-	
Emergency / Parking	0.7	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60 R16	95H	MRF	Wanderer	V	2523	4 mm
Front Right	215/60 R16	95H	MRF	Wanderer	V	2423	4 mm
Rear Left	215/60 R16	95H	MRF	Wanderer	V	2523	4 mm
Rear Right	215/60 R16	95H	MRF	Wanderer	V	2523	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Electrical Components and Instruments: Radio not working.

Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Minor dents and scratches on body panels. Residual traces of repair on body panels.

Undercarriage: Vehicle undercarriage dirty

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026

[illegible]

Brake and shock absorber report

Diagnostic report page 1

/Kia/SONET(D7)		Test Time: 2024-06-16 16:03:06	Report ID: MAXIA30269916140099
B1102:00	Battery voltage low	History	
EPS (Motor Driven Power Steering) (1 DTC)			
DTC	Description	Status	
C1102:16	Battery voltage low	History	
Technician Notes 201729914			
Customer name:			
Technician:			
Date:			
Note: Please show a copy of this report for your records.			

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:

2017299879

DATE

16/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Triangle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:

2017299879

DATE

16/09/2026



No license disc



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026



Water level



Water level



Radio/CD/USB



Door Sealing Rubber Front Right



Seat Front Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249



CONDITION REPORT



Report No:

2017299879

DATE

16/09/2026



Bonnet



Seat Front Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249




CONDITION REPORT



Report No:
2017299879
DATE
16/09/2026



Windscreen Wiper



Service Brake Performance Rear Axle



Tyre Rear Right



Engine



Rear Fender Right / Inner Tray



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249

**CONDITION REPORT**

Report No:
2017299879
DATE
16/09/2026



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MZBFC814TPN333249