



CONDITION REPORT



Report No:

2017282653

DATE

12/08/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	12/08/2026		M57 Pretoria Road - 1619
Inspection Date	12/08/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	LAND ROVER	Registration Number	HLT714FS
Model	DISCOVERY 4 3.0 TDV6 HSE 4X4 DSL AT [2011-2013]	Register Number	
		Date Of First Licensing	
VIN	SALLAAAF3CA600142	Last COR	
Engine Number		License Expiry Date	31/05/2021
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2011	Fuel	DIESEL
Km Reading	247,664 KM	Transmission	AUTOMATIC
Cab / Body Type	SUV		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:

2017282653

DATE

12/08/2026

Damage

Repair Way

Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Windscreen Wiper Damaged	Replace
Seat Front Right Worn	Replace
Seat Rear Worn	Repair
Door Panel Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Air Suspension Front Left Defective	Replace
Air Suspension Front Right Defective	Replace
Air Suspension Rear Left Defective	Replace
Air Suspension Rear Right Defective	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Engine to silencer pipe Welded	Replace
Gearbox Oil Leak	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/55R19	111H	Pirelli	Radial	V	0913	0 mm
Front Right	255/55R19	111H	Pirelli	Radial	V	0118	0 mm
Rear Left	255/55R19	111V	Hilo	Radial	V	1621	2 mm
Rear Right	255/55R19	111V	Hilo	Radial	V	0920	1 mm
Spare	255/55R19	111H	Pirelli	Radial	V	5117	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM	P0700-00	TRANSMISSION CONTROL SYSTEM (MIL REQUEST).	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Electrical Components and Instruments: Vehicle electronics malfunctioning. air suspension compressor missing.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT




Report No:


Report No.
2017282653

DATE _____


12/08/2026




Shock Test




Diagnostic report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT




Report No:


2017282653

DATE

12/08/2026




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



AUTOMATIC



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



LICENSE DISC




VIN PLATE OR STICKER



ENGINE 1



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 10

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



Door Rear Right




Door Front Right



Rear Fender Right



Front Fender Right



Seat Front Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



Spare Tyre



Windscreen Wiper



Windscreen Wiper



Air Suspension Front Left



Air Suspension Front Right



Air Suspension Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



Air Suspension Rear Right




Tyre Rear Right



Tyre Front Right



Tyre Front Left



Engine to silencer pipe



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142



CONDITION REPORT



Report No:
2017282653
DATE
12/08/2026



Tyre Front Right



Door Panel Front Right



Central Air Vent



Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALLAAAF3CA600142