



CONDITION REPORT



Report No:
2017302331
DATE
22/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/09/2026		M57 Pretoria Road - 1619
Inspection Date	22/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	LAND ROVER	Registration Number	KH07JCGP
Model	RANGE ROVER EVOQUE 2.2 SD4 DSL DYNAMIC 4WD AT [2011-2013]	Register Number	
VIN	SALVA2AD3CH660726	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	WHITE	Power / Displacement	
Year Model	2012	Paint Finish	C - COMMON
Km Reading	204,144 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:
2017302331
DATE
22/09/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Switch Electrical Window Winder rear right Damaged	Repair
Seat Rear Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Replace
Stabilizer Mounting Front Right Damaged	Replace
Tyre Front Left Smooth	Replace
Tyre Front Right Smooth	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R20	103Y	Anchee	AC	V	4023	0 mm
Front Right	245/45R20	103Y	Anchee	AC	V	4023	1 mm
Rear Left	245/45R20	103Y	Anchee	AC	V	4023	6 mm
Rear Right	245/45R20	103Y	Anchee	AC	V	4023	6 mm
Spare	T155/85R18	115M	Continental	Temporary	V	//////	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:
2017302331
DATE
22/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	POWERTRAC CONTROL MODULE	P0620-00	GENERATOR CONTROL CIRCUIT	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Bottom of engine is fully covered.

Body • Exterior: Signs of spray work done on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: SALVA2AD3CH660726




CONDITION REPORT




Report No:
2017302331
DATE
22/09/2026




Shock test




Diagnostics report




Diagnostics report



Diagnostics report



Diagnostics report



Diagnostics report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT




Report No:

2017302331

DATE

22/09/2026



Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:

2017302331

DATE

22/09/2026



Automatic transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT




Report No:


2017302331

DATE

22/09/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:
2017302331
DATE
22/09/2026



ENGINE 1



ENGINE 2



CHASSIS



REAR



Expansion bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:

2017302331

DATE

22/09/2026



Front Fender Right



Door Rear Left



Door Front Left



Windscreen



Water level



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:
2017302331
DATE
22/09/2026



Rim Front Right



Stabilizer Mounting Front Right



Tyre Front Right



Front Bumper



Front Bumper



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:

2017302331

DATE

22/09/2026



Rim Front Left



Door Rear Left



Rear Fender Left



Rear Fender Right



Boot Lid / Hatch door



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726



CONDITION REPORT



Report No:

2017302331

DATE

22/09/2026



Rear bumper



Engine



Door Front Left



Seat Rear



Switch Electrical Window Winder rear right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3CH660726