



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/09/2026		M57 Pretoria Road - 1619
Inspection Date	29/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RANGE ROVER	Registration Number	DV71NWGP
Model	EVOQUE	Register Number	
VIN	SALVA2AD3FH044688	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	138,169 KM	Fuel	DIESEL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:

2017304612

DATE

29/09/2026

Damage

Repair Way

Engine Wiring Defective	Repair
Battery box Damaged	Replace
Air cleaner Damaged	Replace
Air Conditioner Insufficient	Replace
Indicator Light Front Right Damaged	Replace
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Fog Light Front Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Defective	Repair
Seat Belt Front Right Defective	Replace
Door Handle Front Right Damaged	Replace
Dash Padding Damaged	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Left / Inner Tray Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Damaged	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Radiator Cradle Damaged	Replace
Gear Selections Slippy Hesitation	Repair
Signs of Vehicle Airbags deployed	Replace
Airbag warning light illuminated on dashboard	Repair
Fan Cowley damaged	Replace
Rear tyres size differs	Replace

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/45 R20	105V	Hify	Vigorous	V	3224	3 mm
Front Right	255/45 R20	105V	Hify	Vigorous	V	3224	5 mm
Rear Left	255/45 R20	105V	Hify	Vigorous	V	3224	5 mm
Rear Right	245/45Z R20	103Y	Annaite	AN606	V	0725	5 mm
Spare	T155/85 R18	115M	Continental	Temporary	V	0415	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	U0405-84	INVALID DATA SENT FROM SPEED CONTROL MODULE	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Lights: Front right headlight lens faded.
Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels.
Undercarriage: Signs of oil leak on engine splash plate. Bottom of engine and gearbox fully covered. Cannot pin direction of oil leak.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:

Report No.
2017304612

DATE _____

29/09/2026

[illegible]

Shock absorber report



Autolab

Autolab is a leading provider of vehicle diagnostic equipment and software solutions for the automotive industry. Our products are designed to help technicians diagnose and repair vehicles quickly and accurately.

Autolab Vehicle Diagnostic Equipment

- Autolab 1000: A comprehensive diagnostic tool for all major vehicle brands.
- Autolab 2000: A more advanced diagnostic tool with additional features.
- Autolab 3000: A professional-grade diagnostic tool for heavy-duty vehicles.
- Autolab 4000: A specialized diagnostic tool for luxury and performance vehicles.

Autolab also offers a range of software solutions, including:

- Autolab Diagnostic Software: A powerful software package for diagnosing vehicle problems.
- Autolab Repair Software: A software package for managing vehicle repairs.
- Autolab Training Software: A software package for training technicians.

Autolab is committed to providing the highest quality products and services to our customers. We are proud to be a leader in the automotive diagnostic industry.

Autolab is a leading provider of vehicle diagnostic equipment and software solutions for the automotive industry. Our products are designed to help technicians diagnose and repair vehicles quickly and accurately.

Autolab Vehicle Diagnostic Equipment

- Autolab 1000: A comprehensive diagnostic tool for all major vehicle brands.
- Autolab 2000: A more advanced diagnostic tool with additional features.
- Autolab 3000: A professional-grade diagnostic tool for heavy-duty vehicles.
- Autolab 4000: A specialized diagnostic tool for luxury and performance vehicles.

Autolab also offers a range of software solutions, including:

- Autolab Diagnostic Software: A powerful software package for diagnosing vehicle problems.
- Autolab Repair Software: A software package for managing vehicle repairs.
- Autolab Training Software: A software package for training technicians.

Autolab is committed to providing the highest quality products and services to our customers. We are proud to be a leader in the automotive diagnostic industry.

Diagnostic report page 1

[illegible]

Diagnostic report page 2

[illegible]

Diagnostic report page 3

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:

2017304612

DATE

29/09/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



RF TYRE TREAD



Spare Wheel



Spare Wheel Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



Front chassis



Rear chassis



Fan Cowley



Oil cap and dipstick



Tail Light Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



Door Rear Left



Door Front Left



Dash Padding



Seat Belt Front Right



Door Handle Front Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:

2017304612

DATE

29/09/2026



Front Fender Right



Rear Fender Right



Front Fender Left



Headlight Left



Headlight Right



Air Conditioner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



Battery box



Engine Wiring



Bonnet slam plate (Shock tower/ Inner tray)



Air cleaner



Fog Light Front Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



Front Bumper



Front Bumper



Front Bumper



Grill



Front Fender Left / Inner Tray



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688



CONDITION REPORT



Report No:
2017304612
DATE
29/09/2026



Control Arm Bush(es) Front Axle Left



Radiator Cradle



Engine Wiring



Door Front Right



Indicator Light Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SALVA2AD3FH044688