



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/05/2025		M57 Pretoria Road - 1619
Inspection Date	22/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	JF99NHGP
Model	CLIO	Register Number	
VIN	VF15RSV0A63319651	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2024
Color	RED	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	102,784 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Indicator Light Front Left Malfunction	Repair
Bright Light Left Malfunction	Repair
Headlight Right Damaged	Repair
Seat Front Right Damaged	Repair
Number Plate Front Missing	Repair
Side Mirror Left Residual Traces of Repair	Repair
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
A • Pillar Left Residual Traces of Repair	Repair
A • Pillar Right Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

 DATE
22/05/2025

Damage	Repair Way
Sill Panel Left Dented	Repair
Sill Panel Right Dented	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Front Left Torn / Cut	Repair
Tyre Front Right Smooth	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Defective	Repair
Rim Front Left Dented	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Repair
Battery loose	Repair
2 spare batterys in the boot	repair
Both front fender liner damage	Replace
Engine management lights illuminated	Repair
Rear tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.6	2.8	-	
Rear	1.8	2.0	-	
Emergency / Parking	1.3	1.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/40R17	84W	Sumitomo	Bc100	V	2321	3 mm
Front Right	205/40R17	84W	Velocity	Speed max	V	4519	0 mm
Rear Left	205/45R17	88V	Michelin	Primacy	V	0315	2 mm
Rear Right	205/50R17	93W	Atlas	Sport green	V	0418	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE	DTC800113	DRIVER'S FRONT AIRBAG CIRCUIT 1 OPEN CIRCUIT	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of poor repair work done on all body panels. Vehicle got some scratches, stone chips and dents.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025**Technician**

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

Shock and brake report



Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



No spare wheel



Battery loose



Oil cap and dipstick



Expenditure bottle

Brake test	
Front axle	1.31 kN
Parking brake	2.68 kN
Final evaluation state	1.85 kN
Rear axle	2.05 kN
Difference	0.20 kN
Total weight	11.96 kN

Shock absorber test (puls2000)	
Front axle	0.15 m/km
Rear axle	0 m/km
Difference	0.15 m/km
Weight	673 kg
403 kg	
25 %	

Parking Brake Performance



Water level

DEKRA Automotive (PTY) Ltd
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

Headlight Right



Bonnet



A • Pillar Left



Seat Front Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

Door Front Right



Front Fender Right



Sill Panel Right



A • Pillar Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

Number Plate Front



Side Mirror Left



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025


Sill Panel Left



Rear bumper



Boot Lid / Hatch door



Tyre Front Right



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651



CONDITION REPORT

Report No: 2016887184

DATE
22/05/2025

Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Rim Front Left



Indicator Light Front Left



Bright Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A63319651