



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/09/2026		M57 Pretoria Road - 1619
Inspection Date	28/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	PEUGEOT	Registration Number	DF51LBGP
Model	RCZ 1.6 3-DR COUPE AT [2013-2016]	Register Number	
VIN	VF34J5FVADP007710	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/05/2026
Color	BLACK	Power / Displacement	
Year Model	2014	Paint Finish	TWO COAT UNI
Km Reading	172,662 KM	Fuel	PETROL
Cab / Body Type	COUPE	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Caps Damaged	Replace
Bonnet stay and shocks Damaged	Replace
Radio/CD/USB Defective	Repair
Switch Electrical Window Winder front left Malfunction	Replace
Switch Electrical Window Winder front right Malfunction	Replace
Air Conditioner Insufficient	Repair
Fog Light Front Right Damaged	Replace
Brake Light Centre Cracked	Replace
Headlight Right Damaged	Replace
Seat Front Right Damaged	Repair
Dash Padding Defective	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Replace
Door Front Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Damaged	Repair
Shock Absorber Front Left Sweat	Replace
Shock Absorber Rear Right Sweat	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Damaged	Replace
Engine to silencer pipe Damaged	Replace
Silencer Missing	Replace
Engine Performance Idling / Hunting	Repair
Gear Selections Slippy Hesitation	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Loose sound wiring inside boot of vehicle	Replace
Spare Wheel missing	Replace
Signs of vehicle overheating	Repair
Front left and right tyres regrooved	Replace
Warning lights illuminated on dashboard	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.56	3.66	-	
Rear	2.93	3.06	-	
Emergency / Parking	1.74	1.98	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40 R19	93W	Bridgestone	Turanza	V	1723	0 mm
Front Right	225/40 R19	93W	Bridgestone	Turanza	V	4322	0 mm
Rear Left	255/35Z R19	96Y	Radar	Dimax	V	1323	0 mm
Rear Right	255/35 R19	92Y	Bridgestone	Turanza	V	2322	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BUILT-IN SYSTEMS INTERFACE(BSI)	F40A	OIL GAUGE FAULT.	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine fan malfunction.
Electrical Components and Instruments: Front right headlight washer cover missing. Radio not working.
Interior: Front left seat adjuster handle missing.
Body • Exterior: Dents and scratches on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710

**CONDITION REPORT**

Report No:
2017304158
DATE
28/09/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:

2017304158

DATE _____

28/09/2026

[illegible]

Brake and shock absorber report

AUTEL  **ASIST**  **ASIST**

ASIST VEHICLE INFORMATION

Report: VEHICLE DIAGNOSTIC REPORT

Vehicle Information

VIN: 1C3CRRH26H550000000
 Year: 2005
 Make: DODGE
 Model: RAM
 Engine: 3.7L Gas
 Transmission: 4L60E
 Mileage: 100000
 Country: USA

2. Diagnostic Trouble Codes (DTC)

DTC	Description	Status
P0013	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Open	P
P0014	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Open	P
P0015	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Closed	P
P0016	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Closed	P
P0017	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Open	P
P0018	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Open	P
P0019	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Closed	P
P0020	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Closed	P
P0021	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Open	P
P0022	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Open	P
P0023	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Closed	P
P0024	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Closed	P
P0025	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Open	P
P0026	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Open	P
P0027	Exhaust Valve Control Solenoid Valve (Bank 1) Stuck Closed	P
P0028	Exhaust Valve Control Solenoid Valve (Bank 2) Stuck Closed	P

ASIST  **ASIST**

Diagnostic report page 1

[illegible]

Diagnostic report page 2

[illegible]

Diagnostic report page 3

Hyundai K2	Test Date: 2026-09-28 16:31:03	Report ID: MAUSA20260928163103
B1105	Illumination failure of left discharge bulb (bulb or bulb igniter)	Intermittent
B1116	ECU fault - ECU supply voltage too low	Intermittent
Engine wiring housing - BSM (1 DTC)		
P10	Exhaustion	Stable
C002	Right front turn lamp fault - Open circuit	
Technician Notes		
20170818		
Customer Name: _____		
Technician: _____		
Date: _____		
Notes: Please send a copy of this report for your records.		

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT




Report No:
2017304158
DATE
28/09/2026



Loose sound wiring



Triangle



Oil cap and dipstick



Headlight Right



Engine Wiring



Caps

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Water level



Bonnet stay and shocks



Bonnet stay and shocks



Door Front Right



Door Front Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:

2017304158

DATE

28/09/2026



Rear Fender Right




Rear bumper



Rear bumper



Boot Lid / Hatch door



Boot Lid / Hatch door



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Rear Fender Left



Radio/CD/USB



Switch Electrical Window Winder front left



Side Mirror Left



Switch Electrical Window Winder front left



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Front Bumper



Fog Light Front Right



Dash Padding



Air Conditioner



Grill



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Front Fender Left / Inner Tray



Shock Absorber Front Left



Tyre Rear Right



Engine



Tyre Front Right



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Sill Panel Left



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Engine to silencer pipe



Engine to silencer pipe



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT




Report No:
2017304158
DATE
28/09/2026



Silencer



Shock Absorber Rear Right



Tyre Rear Left



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Brake Light Centre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710



CONDITION REPORT



Report No:
2017304158
DATE
28/09/2026



Water level



Bonnet



Bonnet



Seat Front Right



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF34J5FVADP007710