



## CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



### Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	01/08/2024		M57 Pretoria Road - 1619
Inspection Date	01/08/2024		Kempton Park - GT

### Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	FH31JSGP
Model	YARIS	Register Number	
VIN	VNKKL0D340A006115	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2021
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	161,005 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

### Vehicle Options & Accessories

#### Items

### VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Windscreen Wiper Missing	Replace
Gear Lever Dust Boot Damaged	Repair
Front Bumper Paintwork • Overspray	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Pitmarks	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Pitmarks	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Overspray	Repair
Rear bumper Paintwork • Scratched	Repair
Roof Paintwork • Pitmarks	Repair
Shock Absorber Rear Right Leak	Replace
Silencer Flange Defective	Repair
Antenna missing	Replace

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

1 / 10



## CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

### Brakes

#### Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	2.8	2.9	-	
Rear	1.9	1.8	-	
Emergency / Parking	1.2	1.3	-	

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/50R15	82V	Dunlop	Sp sport	V	2220	4 mm
Front Right	195/50R15	82V	Dunlop	Sp sport	V	2520	4 mm
Rear Left	185/60R15	84H	Achilles	122	V	4817	3 mm
Rear Right	195/50R15	82V	Dunlop	Sp sport	V	2520	4 mm
Spare	T125/70D15	95M	Yokohama	Temporary	V	////	4 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	B1269	THEFT DETERRENT ECU COMMUNICATION STOP	

### Inspection Conditions

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Vehicle got minor scratches, stone chips and dents. Signs of spray work done on some body panels.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016476675


DATE  
01/08/2024



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

3 / 10



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

4 / 10



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

5 / 10



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

6 / 10



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

8 / 10





LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VNKKL0D340A006115

10 / 10



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024



Coolant bottle



Water level



Windscreen Wiper



Gear Lever Dust Boot



Roof



Rear Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016476675


DATE  
01/08/2024



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za






CONDITION REPORT

Report No: 2016476675

DATE  
01/08/2024



DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016476675**

**DATE**  
**01/08/2024**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za