



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/05/2024		M57 Pretoria Road - 1619
Inspection Date	07/05/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	AUDI	Registration Number	CF13GRGP
Model	A4	Register Number	
VIN	WAUZZZ8K6DA124505	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	29/02/2024
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	363,920 KM	Fuel	DIESEL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Hoses Oil Sweat	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Switch Electrical Window Winder front left Malfunction	Replace
Indicator Light Front Left Defective	Repair
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Right Damaged	Repair
Interior Mirror Missing	Replace
Sun Visor Right Broken	Replace
Door Handle Front Left Defective	Replace
Door Handle Front Right Defective	Repair
Door Handle Rear Right Defective	Repair
Door Sealing Rubber Front Right Damaged	Replace
Steering Wheel Trim Defective	Repair
Number Plate Front Dented	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Residual Traces of Repair	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K6DA124505

1 / 18



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Damage	Repair Way
Windscreen Chipped	Repair
Caliper 1. Axle right Leak	Repair
Brake disc 2. Axle right Defective	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Ball Joint(s) Front Axle Right Defective	Replace
Tyre Front Left Worn	Replace
Tyre Rear Left Defective	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Belly plates Damaged	Repair
Gearbox Mountings Defective	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Triangle Missing	Replace
Electrical instruments and components	Vehicle electronics malfunctioning
Engine	Engine bay dirty and rust inside expansion bottle
Electrical instruments and components	Electronic parking brake switch malfunctioning
Electrical instruments and components	Oil measuring instrument faulty
Engine	Oil cooler dented
Undercarriage	Signs of oil leak on engine splash plate
Undercarriage	Bottom of engine and gearbox fully covered
Undercarriage	Cannot pin direction of oil leak
Undercarriage	Vehicle undercarriage dirty
Brakes	Front right brake disk dust plate damaged
Interior	Vehicle interior dirty and some panels scratched
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Interior	Front left bottom seat adjuster handle damaged

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	3.42	4.46	-	
Rear	2.65	2.01	-	
Emergency / Parking	0.12	2.82	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/50 R17	98W	Hifly	HF805	V	2622	0 mm
Front Right	225/50 R17	98W	Hifly	HF805	V	2622	1 mm
Rear Left	225/50 R17	94V	Michelin	Primacy	V	3919	1 mm
Rear Right	225/50 R17	94V	Michelin	Primacy	V	2921	2 mm
Spare	T125/70 R19	100M	Continental	Temporary	V	3410	4 mm

* Tyre Legend: V=Virgin, R=Recap



CONDITION REPORT

VIN: WAUHZ78K63123456

Report No: 20636956

2 / 18

DATE

07/05/2024

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	U111300	FUNCTION LIMITATION DUE TO RECEIVED MALFUNCTION VA	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016368756

VIN: WAUZZZ8K6DA124505

DATE
3/6/10

3/18
07/05/2024

Brake and shock absorber report

Diagnostic report page 1

Diagnostic report page 2

Category	Sub-Category	Description	Notes
1. General Information	1.1 Basic Information	Project Name: Project Alpha	Project ID: P001
1. General Information	1.2 Project Manager	Project Manager: John Doe	Manager ID: M001
1. General Information	1.3 Project Status	Project Status: In Progress	Progress: 50%
2. Stakeholders	2.1 Internal Stakeholders	Internal Stakeholders: Marketing Department, Sales Department, R&D Department	Count: 3
2. Stakeholders	2.2 External Stakeholders	External Stakeholders: Client A, Client B, Vendor C	Count: 3
3. Scope	3.1 Functional Requirements	Functional Requirements: Feature A, Feature B, Feature C	Count: 3
3. Scope	3.2 Non-Functional Requirements	Non-Functional Requirements: Performance, Security, Usability	Count: 3
4. Schedule	4.1 Milestones	Milestones: Milestone 1, Milestone 2, Milestone 3	Count: 3
4. Schedule	4.2 Timeline	Timeline: Phase 1 (Week 1-4), Phase 2 (Week 5-8), Phase 3 (Week 9-12)	Count: 3
5. Resources	5.1 Human Resources	Human Resources: John Doe, Jane Smith, Michael Johnson	Count: 3
5. Resources	5.2 Financial Resources	Financial Resources: Budget: \$100,000, Actual Spend: \$50,000	Count: 1
6. Risks	6.1 Identified Risks	Identified Risks: Risk A, Risk B, Risk C	Count: 3
6. Risks	6.2 Mitigation Plan	Mitigation Plan: Plan A, Plan B, Plan C	Count: 3
7. Issues	7.1 Open Issues	Open Issues: Issue A, Issue B, Issue C	Count: 3
7. Issues	7.2 Resolution Status	Resolution Status: Resolved, Pending, Open	Count: 3
8. Deliverables	8.1 Core Deliverables	Core Deliverables: Deliverable A, Deliverable B, Deliverable C	Count: 3
8. Deliverables	8.2 Supporting Deliverables	Supporting Deliverables: Deliverable D, Deliverable E, Deliverable F	Count: 3
9. Metrics	9.1 Key Performance Indicators	KPIs: KPI A, KPI B, KPI C	Count: 3
9. Metrics	9.2 Performance Data	Performance Data: Data A, Data B, Data C	Count: 3

Diagnostic report page 3

Auth: Audi A4/C4/PD4 USA/CAU/030902	Date/Time: 2004-05-01 10:31:42	Report ID: MultiDiagData01/030902
77 - Telephone (2 BITEs)		
010	Description:	Status:
000332.002	Supply voltage - Lower limit not reached	Passive/Spare/Bc
00446.002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Spare/Bc
Technician Notes		
20040501n:		
Customer name: _____		
Technician: _____		
Date: _____		
Note: Please save a copy of this report for your records.		

Diagnostic report page 4



FRONT RIGHT CORNER



CONDITION REPORT

Report No: 2016368756

DATE

VIN: WAUZZZ8K670152024

67/0152024

4 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

5 / 18



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic transmission



90 DEGREE FRONT



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

6 / 18



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

8 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 201636875

DATE
07/05/2024

RF TYRE TREAD



Spare wheel



Spare wheel Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

10 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Front chassis



Rear chassis

WAUZZZBK6DA124505
11 / 18

Electronic parking brake swtch



Oil measuring instrument



Oil cooler



Front right brake disk bust pl



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

12 / 18



CONDITION REPORT


Report No: 2016368756

DATE
07/05/2024

Front left bottom seat adjuste



Oil cap



Parking Brake Performance



Front Bumper



Front Bumper



Bonnet



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

14 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Number Plate Front



Headlight Left



Headlight Right



Windscreen



Front Fender Left



Side Mirror Left



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

16 / 18



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Door Front Left



Rear Fender Left

VIN: WAUZZZ8K6DA124505

17 / 18



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Right



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

VIN: WAUZZZ8K6DA124505

18 / 18



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Door Rear Right



Door Front Right



Side Mirror Right



Seat Front Right



Door Sealing Rubber Front Right



Door Handle Front Right





CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Center Console / Cubbyhole + Lid



Front Fender Right



Water level



Hoses



Sun Visor Right



Interior Mirror



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Steering Wheel Trim



Door Handle Rear Right



Door Handle Front Left



Indicator Light Front Left



Rim Front Right



Control Arm Bush(es) Front Axle Right



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Rim Rear Right



Brake disc 2. Axle right



Rim Rear Left



Rim Front Left



Control Arm Bush(es) Front Axle Left



Tyre Front Left



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Control Arm Bush(es) Front Axle Left



CV Joint(s) Boot(s) Front Left (inner/outer)



Caliper 1. Axle right



Ball Joint(s) Front Axle Right



Engine



Belly plates



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

Belly plates



Tyre Rear Left



Gearbox Mountings



Center Console / Cubbyhole + Lid



Switch Electrical Window Winder front left



Switch Electrical Window Winder front left



CONDITION REPORT

Report No: 2016368756

DATE
07/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za