

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	18/04/2024		M57 Pretoria Road - 1619
Inspection Date	18/04/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	AUDI	Registration Number	KL41YMGP
Model	Q5	Register Number	
VIN	WAUZZZ8R5HA074697	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2024
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	151,052 KM	Fuel	DIESEL
Cab / Body Type	SUV	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Central Air Vent Damaged	Repair
Carpet Front Damaged	Repair
Side Mirror Left Damaged	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Rear bumper Damaged	Repair
Shock Absorber Rear Right Leak	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Some interior panels damaged	Replace
Some interior panels missing	Replace
Engine management lights illuminated	Repair
Electronic handbrake malfunctioning	Repair

Brakes**Brake Test Results**

No Brake Test on a brake test machine has been performed.

	Left	Right	Axe Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	-	-	-	-
Rear	-	-	-	-
Emergency / Parking	-	-	-	-

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	275/35R20	102Y	Goodyear	Excellence	V	4920	0 mm
Front Right	275/40R20	106W	Federal	Radial	V	4810	0 mm
Rear Left	245/45R20	115R	Kumho	Radial	V	4420	0 mm
Rear Right	255/55R18	109V	Continental	Contisport	V	4214	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: SIGNS OF REPAIR WORK DONE TO SOME BODY PANELS. POOR ALIGNMENT TO SOME BODY PANELS.ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE
ENGINE COVERED.

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024



Oil cap.



Automatic.



Undercarriage front.



Undercarriage rear.



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024



ODOMETER



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



ENGINE 1



CONDITION REPORT

Report No: 2016346670


DATE
18/04/2024




VIN PLATE OR STICKER




LICENSE DISC



SHOCK REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2




DIAGNOSTIC REPORT PAGE 3




CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024



DIAGNOSTIC REPORT PAGE 4



DIAGNOSTIC REPORT PAGE 5



Water level



Front Bumper



Front Bumper



Bonnet



CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024



Front Fender Left



Door Front Left



Side Mirror Left



Door Rear Left



Rear bumper



Rear bumper



CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024



Front Fender Right



Door Front Right



Carpet Front



Carpet Front



Side Mirror Right



Central Air Vent



CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024



Shock Absorber Rear Right



Tyre Front Right



Tyre Front Left



CONDITION REPORT

Report No: 2016346670

DATE
18/04/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za