



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	04/06/2024		M57 Pretoria Road - 1619
Inspection Date	04/06/2024		Kempton Park - GT


Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	DV83MHGP
Model	FOCUS ST	Register Number	
VIN	WF0KXXGCBKCT27876	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2023
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	123 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Repair
Fog Light Front Left Damaged	Replace
Fog Light Front Right Malfunction	Repair
Side Mirror Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Flaking	Repair
Front Fender Right Paintwork • Pitmarks	Repair
Rear Fender Left Cracked	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Fuel Flap Damaged	Replace
Roof Dented	Repair
Tie Rod End right Damaged	Replace
Tyre Front Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Main Beam Left Welded	Repair
Main Beam Right Welded	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Defective	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0KXXGCBKCT27876

1 / 14



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

Damage

Cluster malfunction can not see mileage
Diagnostic report pick up the mileage
Aftermarket air filter fitted
Body exterior
Body exterior
Water leak

Repair Way

Repair
Repair
Repair
Signs of spray work done on some body panels
Vehicle is cut and join
bottom of engine can't pin point water

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.3	4.1	-	
Rear	2.4	2.4	-	
Emergency / Parking	1.5	1.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R18	92W	Timax	Eco sport 59	V	5119	0 mm
Front Right	225/40R18	92W	Timax	Eco sport 59	V	3719	4 mm
Rear Left	255/35R18	94W	Nexen	N fera	V	1416	3 mm
Rear Right	255/35R18	94Y	Continental	Contact	V	2217	0 mm
Spare	T125/85R16	99M	Maxxis	Temporary	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


VIN: WFOKXXGGBKCT37876

Report No: 2016403928

2 / 14

DATE

04/06/2024



Shock and brake report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



CONDITION REPORT

Report No: 2016403928

VIN: WF0KXXGCBKCT27876

DATE

04/06/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
VIN: WF0KXXGCBKCT27875
04/06/2024
4 / 14



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



CONDITION REPORT

Report No: 2016403928

DATE

04/06/2024

VIN: WF0KXXGCBKCT27876

5 / 14

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

VIN: WF0KXXGCBKCT27876

6 / 14



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

**CONDITION REPORT****Report No: 2016403928****DATE**
04/06/2024

VIN: WF0KXXGCBKCT27876

7 / 14

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

RF TYRE TREAD



Spare wheel

VIN: WF0KXXGCBKCT27876

8 / 14



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

VIN: WF0KXXGCBKCT27876
9 / 14

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

CHASSIS




Oil cap and dipstick



Aftermarket air filter fitted



Expansion bottle



Water level



Bonnet



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

VIN: WF0KXXGCBKCT27876

11 / 14

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024


Roof



Side Mirror Right

VIN: WFAKXXGCBKCT27876

12 / 14



Rear Fender Right



Fuel Flap



Door Rear Right



Door Front Right



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

VIN: WF0KXXGCBKCT27876

13 / 14

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

Front Fender Right



Front Bumper



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear bumper



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024


Inner Boot Floor Pan and Spare Wheel Well



Tyre Rear Right



Main Beam Left



Main Beam Right



Engine



Engine



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

Engine



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Radiator Cradle



Tie Rod End right



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016403928

DATE
04/06/2024

Main Beam Right



Tyre Front Left



Central Air Vent



Fog Light Front Left



Fog Light Front Right

**CONDITION REPORT****Report No: 2016403928****DATE**
04/06/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za