



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	13/03/2024		M57 Pretoria Road - 1619
Inspection Date	13/03/2024		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MINI	Registration Number	JP36MXGP
Model	COOPER S	Register Number	
VIN	WMWMM320X0TN78817	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/07/2022
Color	BROWN	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	161,102 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Replace
Hoses Damaged	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Sun Visor Left Damaged	Replace
Sun Visor Right Damaged	Repair
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Damaged	Repair
A • Pillar Right Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Right Damaged	Repair
Windscreen Damaged	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Leak	Repair
Radiator Cradle Damaged	Replace
Body and exterior	Minor dents and scratches and stone chips.
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Poor alignment to some body panels.
Body and exterior	Signs of impact damage to front of vehicle.
Body and exterior	Vehicle body in poor condition.
Vehicle	Vehicle electronics malfunctioning.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WMWMM320X0TN78817

1 / 12



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

### Brakes

#### Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	3.2	3.19	-	-
Rear	2.14	2.26	-	-
Emergency / Parking	1.52	1.57	-	-

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/45R17	88W	Pacek	Radial	V	0615	1 mm
Front Right	205/45R17	88W	Pacek	Radial	V	0615	1 mm
Rear Left	225/45R17	94W	Wanli	Radial	V	3119	0 mm
Rear Right	205/45R17	88W	Achilles	Radial	V	0513	0 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



## CONDITION REPORT


VIN: WMMWV1N3016304290

Report No. 2016304290

2 / 12

DATE

13/03/2024




Brake and shock test




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER

**CONDITION REPORT****Report No:** 2016304290

VIN: WMWMM320X0TN78817

**DATE**

13/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016304290

DATE

VIN: WMWMM320X9703/2024

4 / 12



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

VIN: WMWMM320X0TN78817

5 / 12

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

VIN: WMWMM320X0TN78817

6 / 12



90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

VIN: WMWMM320X0TN78817

7 / 12

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 11



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

VIN: WMWMM320X0TN78817

9 / 12



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

Oil cap and dipstick



Hoses



Hoses



Water level



Engine Wiring



Engine Wiring



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

VIN: WMMWMM320X0TN78817

11 / 12



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

Front Bumper



Front Bumper



Grill



Bonnet



Front Fender Left



Door Front Left



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

Rear Fender Left



Windscreen Wiper



Windscreen Wiper



Front Fender Right



Rear Fender Right



Door Rear Right



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

Door Front Right



A • Pillar Right



Sun Visor Left



Sun Visor Right



Windscreen



Tyre Rear Left



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

Tyre Rear Right



Engine



Gearbox



Hoses



Radiator Cradle



Tail Light Left



## CONDITION REPORT

Report No: 2016304290

DATE  
13/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)